



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74570
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74570

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:

Author: BJW

Location: 0826 BH TO CLOSE

Stock #: 2105R

Stock Desc: 2024 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG16RW102280

Serial #: 4YDTSGG16RW102280

Mileage:

Licence:

Invoice #:

Date In: 19 AUG 24

Promised: 31 AUG 24

Date Sched:

Completed: 27 AUG 24

Warr. Date:

Job #1 - Warranty

COMPLAINT: TODD ADVISED THAT THERE IS WATER LEAKING DOWN FROM THE A/C UNIT INTO THE BED AND THE FLOOR.

CAUSE: Drain hole was clogged

CORRECTION: Inspected the ac in the wall. Noticed the floor of the ac was full of water. When the ac was on the fan would kick the water out of the ac. This causing water to be splashed the the hole for the electrical cord and onto the bed. Unplugged the ac then unscrewed the trim and ac from the wall. Pulled out the ac then inspected the bottom of the ac, found the drain hole clogged with debree. Cleaned out the hole of debree. Mounted the ac back in the wall and plugged in the power. Now ac can drain off the condensation. Powered on the ac and let it run. Checked the ac the following morning, found no pool of water.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	SAR	170.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Subtotal for Job #1: 170.00

Parts Total: 0.00
Labour Total: 170.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 170.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Aug 2024



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

