



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74720
Promised Date:
20 SEP 24

CUSTOMER WORK ORDER

WO #: 74720

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: BH - PARTS ORDERED. 9-6-24
Author: BH
Location: 1022 BH TO CLOSE

Stock #: 11392
Stock Desc: 2024 5W KEYSTONE
MONTANA HIGH COUNTRY 389BH
Chassis #: 4YDFHMT25RA741417
Serial #: 4YDFHMT25RA741417
Mileage: 0
Licence:

Invoice #:
Date In: 05 SEP 24
Promised: 30 SEP 24
Date Sched:
Completed: 22 OCT 24
Warr. Date:

Job #1 - Warranty

COMPLAINT: THE DOOR TO THE BED ROOM WILL NOT CLOSE AND THE WOOD BOARD IS BOWED

CAUSE: The frame for the door was warped badly

CORRECTION: Removed the frame and cut new boards and installed then reinstalled panels and new trim work then mounted door and filled nail holes.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	0.00
Z990	MISCELLANEOUS REPAIR	BRM	0.00
Z990	MISCELLANEOUS REPAIR	BRM	255.00
Z990	MISCELLANEOUS REPAIR	BRM	0.00

Parts

Part #	Description	Qty	Price	Total
681066	Trim - Batten - 3.6mm x 7/8" x 96" -	2.00	2.30	4.60
681083	Seam - Tape - 1" - Bermuda Arctic	100.00	0.18	18.00

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-BATTEN	1.00	80.84	80.84
FRT	UPS-SEAM TAPE	1.00	18.60	18.60

Subtotal for Job #1: 377.04

Parts Total: 22.60
Labour Total: 255.00
Sublet Total: 0.00
Extras Total: 99.44
WORK ORDER TOTAL: 377.04

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Oct 2024



Customer #: 1000
BASDEN'S AMERICAN RV,

