



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74787



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 74787

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 1007 CHECK PREAUTH

Stock #: 11468
Stock Desc: 2025 TT ALLIANCE RV
DELTA RK234
Chassis #: 7M5TD2726SC304340
Serial #: 7M5TD2726SC304340
Mileage: 0
Licence:

Invoice #:
Date In: 14 SEP 24
Promised:
Date Sched:
Completed: 30 SEP 24
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: FRONT INTRY DOOR IS HITTING LATCH

CAUSE: door hitting latch

CORRECTION: removed shipping blocks.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: REAR ENTRY DOOR HITTING LATCH

CAUSE: dorr hitting latch

CORRECTION: removed shipping blocks.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C



Subtotal for Job #2: 0.00

Job #3 - Warranty
COMPLAINT: THE BATHROOM GFCI IS LOOSE

CAUSE: bathroom gfci box was not secured to wall.

CORRECTION: took off cover and pulled out outlet and surround cover to get to box,tightened up tabs
against wall to secure box,then put back surround and outlet and secured and put on cover.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	51.00

Subtotal for Job #3: 51.00

Parts Total: 0.00
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 51.00

Thank you for being a valued customer. We appreciate your business.
All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.

Customer Signature : _____

Date: 04 Oct 2024

W/O: 74787



Customer #: 1000
BASDEN'S AMERICAN RV,





600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74787



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 74787
Customer: 1000 - BASDEN'S AMERICAN RV -
Tag:
Author: PH
Location: 1007 CHECK PREAUTH

Stock #: 11468
Stock Desc: 2025 TT ALLIANCE RV
DELTA RK234
Chassis #: 7M5TD2726SC304340
Serial #: 7M5TD2726SC304340
Mileage: 0
Licence:

Invoice #:
Date In: 14 SEP 24
Promised:
Date Sched:
Completed: 30 SEP 24
Warr. Date:

Job #PDINTT - Internal
PDI - NEW TRAVEL TRAILER

Labor			
Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C
Subtotal for Job #PDINTT:				0.00

Job #1 - Internal
COMPLAINT: FRONT INTRY DOOR IS HITTING LATCH

CAUSE: door hitting latch
CORRECTION: removed shipping blocks.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #1:			0.00

Job #2 - Internal
COMPLAINT: REAR ENTRY DOOR HITTING LATCH

CAUSE: dorr hitting latch
CORRECTION: removed shipping blocks.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C



Subtotal for Job #2: 0.00

Job #3 - Warranty
COMPLAINT: THE BATHROOM GFCI IS LOOSE

CAUSE: bathroom gfci box was not secured to wall.

CORRECTION: took off cover and pulled out outlet and surround cover to get to box,tightened up tabs
against wall to secure box,then put back surround and outlet and secured and put on cover.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	51.00

Subtotal for Job #3: 51.00

Parts Total: 0.00
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.

Date: 04 Oct 2024

Customer Signature : _____

W/O: 74787



Customer #: 1000
BASDENS AMERICAN RV,

