

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2068292
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FESB6RW028851
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET274RKS-320
JEFFREY VANDIVER		DEALER RO #	74850
7544 GEORGIA LN		CLAIM START DATE	09/23/2024
Newburgh, IN 47630		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	09/09/2024	WARRANTY EXPIRATION DATE	09/09/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-66-01-17-000668	Entry Door Lock - Exterior/Entry Doors/Replace/Latch		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-23 14:55:44 :: CUSTOMER ADVISES THAT MAIN ENTRY DOOR DEAD BOLT LOCK CYLINDER IS NOT TURNING.. Cylinder had an internal failure. Drilled out lock Cylinder and removed door handle assembly. Recieved new assembly and installed. Additional Note : bhoffman@americanrvcenter.com, 2024-09-23 14:56:29 :: HAD TO DRILL THE LOCK OUT WOULD NOT UNLOCK			
Model#	Dlr Sub Hrs	0.60	Sub Labor Amt	\$102.00
Serial#	Appr Hrs	0.45	Appr Labor Amt	\$76.50
	Notes			
	as per repair code this repair requires photos showing the issue i dont know why it didnt upload but its there drill out dead bolt and R&R entry door lock assembly			

Submitted	Labor Amt	\$102.00	Approved	Labor Amt	\$76.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$102.00		Total	\$76.50

DEALER _____ **DATE** _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____

SIGNATURE

All repairs described have been inspected and are satisfactory.