



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74933
Promised Date:
20 NOV 24

CUSTOMER WORK ORDER

WO #: 74933

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: PH - PARTS ORDERED 1-3-25
Author: PH
Location: 0115 CHECK WORK

Stock #: 11475
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 211BH
Chassis #: 5ZT2CAKB1SU044670
Serial #: 5ZT2CAKB1SU044670
Mileage: 0
Licence:

Invoice #:
Date In: 03 OCT 24
Promised: 30 NOV 24
Date Sched:
Completed: 13 JAN 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*75766 on 03 JAN 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER - 4 HR PDI

CAUSE: Pdi new travel trailer

CORRECTION: I ran all appliances and ran all water lines to find anything wrong with then unit and fix them

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

Transferred to BAS*75766 on 03 JAN 25
Estimate amount was 0.00
X-CHOCKS PER CHAD

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: PASSENGER TAIL LIGHT NOT WORKING

CAUSE: Off door side turn light not working

CORRECTION: I pulled light off wall and found that one of the wires was not conected i then conected and remounted on the wall

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	17.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 68.00

Job #3 - Warranty

COMPLAINT: BOTH SETS OF ELECTRIC JACKS ARE NOT WORKING

CAUSE: Jacks not working

CORRECTION: The front would only run the door side then the rear would only run the off door side i then made sure that both motors had power going to them and they all did but we're not working

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	170.00

Parts

Part #	Description	Qty	Price	Total
F100516332	MOTOR ONLY FOR BAL AUTO LEVELING JAC	2.00	91.08	182.16

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-MOTORS	1.00	13.30	13.30

Subtotal for Job #3: 365.46

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*75592 on 02 DEC 24

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: i first turned valves on water heater then on the pump and ran antifreeze through all lines then made sure all holding tanks were empty

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JG	N/C
Z990	WINTERIZE UNIT	JG	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #WINTER* - Internal

Transferred to BAS*75766 on 03 JAN 25

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



W/O: 74933
Promised Date: 30 NOV 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER*:				0.00

Job #4 - Warranty

COMPLAINT: CITY WATER LEAKING

CAUSE: City water leaking

CORRECTION: I first remov3d screws holding the city water conection and I removed it then replaced with new and pit putty tape around the back and screwed into place and made sure it was not leaking

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	51.00

Parts

Part #	Description	Qty	Price	Total
681162	94214 PW CITY WATER W/BRASS CHECK VA	1.00	11.83	11.83

Subtotal for Job #4: 62.83

Job #5 - Warranty

COMPLAINT: DURING LP LEAKDOWN TEST, TECH FOUND UNIT WILL NOT HOLD PRESSURE

CAUSE: After doing lp drop test found there was a leak

CORRECTION: I first turned gas on and spraied lines conected to the tanks and found that one of the lines going to the tank was not fully tightened so I tightened and then did an lp drop test to be sure there was no more leak

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	17.00

Subtotal for Job #5: 17.00

Parts Total:	193.99
Labour Total:	306.00
Sublet Total:	0.00
Extras Total:	13.30
WORK ORDER TOTAL:	513.29

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Jan 2025

W/O: 74933
Promised Date: 30 NOV 24



Customer #: 1000
BASDEN'S AMERICAN RV,

