

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74960
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 55268 - MICHELLE GOLDMAN
Address:

, IN
Phone: (812) 549-8897
Stock Number: 2021 ACADIA

VIN: HIN: SER#: 4YDF36627ML550195
Mileage: Work Order Comp: 22 OCT 24
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 07 OCT 24 Inv #: 410830

WO # Job # Description JOB INFORMATION

74960 2-445 23-445 IT HAS BEEN DETIREMINED THAT ON CERTAIN REAR LIVING ROOM
MODELS THE REAR WALL IS ATTACHED AT THE ROOF, AND SIDEWALLS, BUT
MAY NOT BE PROPERLY ATTACHED TO THE FLOOR. THE FOLLOWING
PRECEDURE DESCRIBES HOW TO PROPERLY ATTACH THE FLOOR TO THE REAR
WALL.
Put in parts sheet. Waiting on approval. Received parts. Pulled
unit back into shop. Opened slide rooms. Removed mounting screws
for couch. Removed couch from wall. Took metal trim and cut to
length. Removed batten strip. Set Brad nails. Applied liquid
nails to floor and wall. Placed metal against wall and floor.
Drilled out holes on top of metal. Secured metal trim to wall and
floor. Cleaned up area. Secured couch.
.

Part No Job# Description PARTS Qty Price Total

721131 -445 Trim - Metal - 1 1/2" x 1 1/2" x 1.00 22.02 22.02

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 -445 MISCELLANEOUS REPAIR 0.00 170.00 0.00
Z990 -445 MISCELLANEOUS REPAIR 0.03 170.00 5.10
Z990 -445 MISCELLANEOUS REPAIR 0.42 170.00 71.40
Z990 -445 MISCELLANEOUS REPAIR 0.00 170.00 0.00
Z990 -445 MISCELLANEOUS REPAIR 0.25 170.00 42.50

Excode Job# Description EXTRAS Qty Price Total

FRT -445 UPS-TRIM 1.00 78.80 78.80

Claim : 74960

```

*****
Excode   Job#   Description   EXTRAS   Qty   Price   Total
*****

```

```

Parts Total:      22.02
Labour Total:     119.00
Sublet Total:      0.00
Extras Total:      78.80

```

>>>> Claim Total: 219.82

Customer Signature: _____

Date: _____