

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75000
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 54872 - SAMUEL H. NORMAN
Address: 3534 E ST RD 68 HAUBSTADT, IN

47639

Phone: 812-632-8182

Stock Number: 11379 - 2024 SPRINGDALE 260BHC 4YDTSGL28R7104315

VIN: 4YDTSGL28R7104315 HIN: SER#: 4YDTSGL28R7104315

Mileage: 0

Work Order Comp: 24 OCT 24

Auth. No:

Dealer #: 1194

Warr. Date: 07 JUN 24

Work Order Date: 11 OCT 24

Inv #: 410977

WO # Job # Description JOB INFORMATION

75000 2 CUSTOMER ADVISES THAT THE TANKS SENSOR INDICATORS READ ERRATIC.
SOMETIMES HE CAN PUT A LITTLE BIT OF WATER IN THE FRESH TANK
AND IT WILL SHOW FULL. HE CAN FLUSH THE TOILET A COUPLE OF TIMES
AND THE BLACK TANK WILL SHOW HALF FULL. THIS TRAILER IS
EQUIPPED WITH A BLACK 2 AND GREY 2 INDICATOR, BUT IT DOES NOT
HAVE A BLACK 2 OR GREY 2 TANK. HOWEVER CUSTOMER IS GETTING
LEVEL READINGS FOR BOTH OF THOSE TANKS.
Circuit board
Filled the fresh tank 2/3 full then turned on the water pump,
opened the kitchen faucet and let it run. Checked tank levels
after 5 mins and found the kitchen faucet is filling to black 2
tank that it doesn't have. Let the kitchen faucet run for another
2 minutes then checked the tank levels, grey land 2, black land 2
showed 1/3full. Got with Ben about the tanks reading wrong, he
had Matt order a new circuit board for the touch pad. Drained the
grey tank.

Part No Job# Description PARTS Qty Price Total

717692 2 Monitor Panel - Tank Board - For 1.00 28.30 28.30

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 2 MISCELLANEOUS REPAIR 0.00 170.00 0.00
Z990 2 MISCELLANEOUS REPAIR 0.50 170.00 85.00

Claim : 75000

```

*****
Lab Code  Job#  Description      LABOUR              Hrs      Rate      Total
*****
Z990      2    MISCELLANEOUS REPAIR              0.00    170.00      0.00

```

```

*****
Excode    Job#  Description      EXTRAS              Qty      Price      Total
*****
FRT       2    UPS-PANEL BOARD              1.00    16.19      16.19

```

```

Parts Total:      28.30
Labour Total:     85.00
Sublet Total:      0.00
Extras Total:     16.19

```

```

>>>> Claim Total:      129.49

```

Customer Signature: _____

Date: _____