

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75199
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 41599 - CAMERON TURPIN
Address: 8520 CLARENDON DR EVANSVILLE, IN

47725

Phone: 618-262-6439

Stock Number: 11401 - 2024 CATALINA 263BHSCLE 5ZT2CARBXRN300377

VIN: 5ZT2CARBXRN300377 HIN: SER#: 5ZT2CARBXRN300377

Mileage: 0 Work Order Comp: 28 OCT 24

Auth. No: Dealer #:

Warr. Date: 12 OCT 24 Work Order Date: 25 OCT 24 Inv #: 411090

WO # Job # Description JOB INFORMATION

75199 1 TRAILER LIGHT FAULT TAIL LIGTHS ARE NOT WORKING ON THE RIGHT SIDE
PASSANGER SIDE
right turn signal not working
hooked up box and it blew fuse,took out both rear lights and
tested,brown wire going across to pass side was bad,because we
ran wire outside and it would work hook wire to wire and pulled
through wall new wire,hooked up and it worked,put loghts back on
and tested again ,it quit working again,took lights out again and
found on driver side rear brown wire was stuck and when you moved
it it would work off and on,drilled hole in bottom and ran new
brown wire through wall and hooked up,wire had to have staple in
it,tested light and it works now without blowing fuse,installed
lights back in place and siliconed,all good.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 1.70 170.00 289.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.80 170.00 136.00

Excode Job# Description EXTRAS Qty Price Total

SS 1 SHOP SUPPLIES 1.00 0.00 0.00

Parts Total: 0.00
Labour Total: 425.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 425.00

Customer Signature: _____

Date: _____

Claim : 75199

Excode	Job#	Description	EXTRAS	Qty	Price

Total					