



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75263
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75263

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 1202 BH TO CLOSE

Stock #: 11499
Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 269DBC
Chassis #: 4YDTSGM29S7101136
Serial #: 4YDTSGM29S7101136
Mileage: 0
Licence:

Invoice #:
Date In: 30 OCT 24
Promised: 31 DEC 24
Date Sched:
Completed: 30 NOV 24
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*75546 on 26 NOV 24

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterizing 2 gallons

CORRECTION: Drained the black, grey, fresh tanks. Drained the water heater. Added 2 gallons thru the kitchen faucet, bathroom faucet, toilet, shower. Depressed city water connection.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C
Z990	WINTERIZE UNIT	SAR	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: THE ENTRY DOOR WILL NOT LATCH. NOTED ON DELIVERY

CAUSE: ENTRY DOOR WILL NOT LATCH. NOTED ON DELIVERY.

CORRECTION: Removed door frame latch plate. Filed edge of cutout in door frame to allow latch plate to adjust and let entry door latch closed. Remounted latch plate and checked operation. Entry door new latching closed.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00
Subtotal for Job #1:			34.00

Job #2 - Internal

WINTERIZE UNIT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #2:			0.00

Job #3 - Warranty

COMPLAINT: WINTERIZED HOSE HAS 2 BENDS IN IT

CAUSE: WINTERIZING HOSE HAS (2) BENDS IN IT. HOSE IS PINCHED FLAT.

CORRECTION: Cut off hose past shut off to allow for new hose to be attached with a 90 deg. fitting to eliminate two bends in hose. Cut new hose to fit and installed with clamps. Checked all hose clamps for leaks. No leaks found.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	170.00

Parts

Part #	Description	Qty	Price	Total
8910	REINFORCED PVC TUBING, 1/2IN ID X 5/	4.00	0.86	3.44
30840	30840 PEXLock; 1/2 Inch PEX x 1/2 In	1.00	1.67	1.67
Subtotal for Job #3:				175.11

Parts Total:	5.11
Labour Total:	204.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	209.11



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Dec 2024

W/O: 75263
Promised Date: 31 DEC 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Promised Work
Order

