

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75264
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 55093 - DARREN MCCOMBS
Address: 3114 PARADISE CIRCLE NEWBURGH, IN

47630

Phone:

Stock Number: 11496 - 2025 AVENUE 23ML 7M5FA2821SA009937

VIN: 7M5FA2821SA009937 HIN:

SER#: 7M5FA2821SA009937

Mileage: 0

Work Order Comp: 11 DEC 24

Auth. No:

Dealer #:

Warr. Date: 31 OCT 24

Work Order Date: 30 OCT 24

Inv #: 412643

WO # Job # Description JOB INFORMATION

75264 3 THERE IS NO POWER GOING TO THE THERMOSTAT. ROBBED PARTS FROM
VIN#7M5FA3323SA009712 (AVENUE)
no power going to thermostat
pulled off thermostat checked wires and no power, took off panels
to ac and checked wires and no power to it. traced wire through
ceiling down wall to bluetooth panel, unhooked power wire and ran
power around bluetooth and we have power, hooked bluetooth panel
and it blows fuse, bluetooth panel has a short in it, went and
robbed another one from another unit and installed it and now i
have power to bluetooth panel and thermostat, put back together
and it works fine now.

75264 4 THE MONITOR PANEL FOR THE BATTERY, FRESH, GREY, AND BLACK TANKS
HAS POWER GOING TO IT, BUT NOTHING LIGHTS UP. ROBBED PARTS FROM
VIN#7M5FA3323SA009712 (AVENUE)
monitor panel doesn't work for battery, fresh, black, and grey tank.
checked ground and power and they are good, went and robbed
another panel and it works like it should, monitor is bad, put
everything back together.

75264 5 THE BLACK TANK FLUSH IS NOT WORKING.
no water to black tank flush
took line off to vacuum breaker and i have water coming through
breaker, will have to check line to tank. cut several places on
underbelly to find water line, found water line in basement
area, took off wall to get to line, cut line and turned on water

Claim : 75264

 WO # Job # Description JOB INFORMATION

 and i could hear air and a little bit of water, cut other side of
 line where it was spliced in and finally got water, looked in line
 and found screw where line was spliced. spliced line back together
 and turned on water and now it works, put wall back in
 place, covered holes in underbelly and installed screws back in
 and tied up breaker vacuum.

75264 1 RR JACK FAULT
 jack fault right rear
 went to auto level and right rear jack had a fault, tried to run
 rear jacks down and it would not work on right rear but it would
 work on left rear, checked plugs on jack and they were
 good, checked control box and wires were hooked up right and fuse
 was good, looked at plug in and ground wire was out of plug in
 about half way pulled out plug and found ground wire was not
 connected in plug put wire back in plug and secured checked again
 and now it works, all good.

75264 2 THERE IS NO POWER GOING TO THE LP DETECTOR.
 no power to lp detector
 installed new fuse and it kept popping it, it had 2 wires going to
 hot side and 2 wires going to ground, checked power to lp detector
 and one wire had power and the other didnt, hooked up wire with
 power to lp detector and it works, someone had a extra wire hooked
 up and it didnt go to it, capped wire off, everything works. it had
 no power to wire. someone could have hooked it to ground.

Part No	Job#	Description	PARTS	Qty	Price	Total
27981	3	Wall Plate - 2 Zone w/HDMI		1.00	74.99	74.99
25982	4	Panel - Monitor - Convenience Cen		1.00	84.99	84.99
BBM94239	5	94239 VACUUM BREAKER/CHECK VALVE		1.00	21.99	21.99
WAT81902914	5	UNION CONNECTOR 1/2"CST		1.00	7.99	7.99

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		1.50	170.00	255.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00

Claim : 75264

```
*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      2    MISC LABOUR CODE (EXTERNAL)          1.00    170.00    170.00
*****
```

```
*****
Excode    Job#  Description          EXTRAS          Qty      Price     Total
*****
FRT       3    FED-EX - JOBS 3,4          1.00     11.80     11.80
*****
```

Parts Total: 189.96
Labour Total: 680.00
Sublet Total: 0.00
Extras Total: 11.80

>>>> Claim Total: 881.76

Customer Signature: _____

Date: _____