



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75264
Promised Date:
30 NOV 24

CUSTOMER WORK ORDER

WO #: 75264

Customer: 55093 - MCCOMBS, DARREN

Stock #: 11496

Stock Desc: 2025 5W ALLIANCE RV
AVENUE 23ML

Chassis #: 7M5FA2821SA009937

Serial #: 7M5FA2821SA009937

Mileage: 0

Licence:

Invoice #:

Date In: 30 OCT 24

Promised: 30 NOV 24

Date Sched:

Completed: 11 DEC 24

Warr. Date: 31 OCT 24

Job #PDINFW - Internal

COMPLAINT: Transferred to BAS*75361 on 07 NOV 24

Estimate amount was 0.00

PDI - NEW FIFTH WHEEL

CAUSE: pdi

CORRECTION: did pdi and everything on sheet,also checked lp.water,electrical,and appliances.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*75361 on 07 NOV 24

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: winterized unit and did everything on sheet,used 2 gallon.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C



Customer #: 55093
MCCOMBS, DARREN

W/O: 75264
Promised Date: 30 NOV 24



Customer #: 55093
MCCOMBS, DARREN



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #FPDINFW - Internal

COMPLAINT: Transferred to BAS*75361 on 07 NOV 24
Estimate amount was 0.00
FINAL PDI ON NEW FIFTH WHEELS

CAUSE: final pdi

CORRECTION: did final and everything on sheet and got model and serial numbers on appliances.

Labor

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL)	DGH	N/C

Subtotal for Job #FPDINFW: 0.00

Job #1 - Warranty

COMPLAINT: RR JACK FAULT

CAUSE: jack fault right rear

CORRECTION: went to auto level and right rear jack had a fault, tried to run rear jacks down and it would not work on right rear but it would work on left rear, checked plugs on jack and they were good, checked control box and wires were hooked up right and fuse was good, looked at plug in and ground wire was out of plug in about half way pulled out plug and found ground wire was not connected in plug put wire back in plug and secured checked again and now it works, all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00

Subtotal for Job #1: 85.00

Job #2 - Warranty

COMPLAINT: THERE IS NO POWER GOING TO THE LP DETECTOR.

CAUSE: no power to lp detector

CORRECTION: installed new fuse and it kept popping it, it had 2 wires going to hot side and 2 wires going to ground, checked power to lp detector and one wire had power and the other didn't, hooked up wire with power to lp detector and it works, someone had an extra wire hooked up and it didn't go to it, capped wire off, everything works. it had no power to wire. someone could have hooked it to ground.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	170.00

Subtotal for Job #2: 170.00

Job #3 - Warranty

COMPLAINT: THERE IS NO POWER GOING TO THE THERMOSTAT.
ROBBED PARTS FROM VIN#7M5FA3323SA009712 (AVENUE)

CAUSE: no power going to thermostat

CORRECTION: pulled off thermostat checked wires and no power, took off panels to ac and checked wires





and no power to it. traced wire through ceiling down wall to bluetooth panel, unhooked power wire and ran power around bluetooth and we have power, hooked bluetooth panel and it blows fuse, bluetooth panel has a short in it, went and robbed another one from another unit and installed it and now i have power to bluetooth panel and thermostat, put back together and it works fine now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
27981	Wall Plate - 2 Zone w/HDMI	1.00	74.99	74.99

Other Services

Code	Description	Qty	Price	Total
FRT	FED-EX - JOBS 3,4	1.00	11.80	11.80

Subtotal for Job #3: 171.79**Job #4 - Warranty**

COMPLAINT: THE MONITOR PANEL FOR THE BATTERY, FRESH, GREY, AND BLACK TANKS HAS POWER GOING TO IT, BUT NOTHING LIGHTS UP. ROBBED PARTS FROM VIN#7M5FA3323SA009712 (AVENUE)

CAUSE: monitor panel dosent work for battery, fresh, black, and grey tank.

CORRECTION: checked ground and power and they are good, went and robbed another panel and it works like it should, monitor is bad, put everything back together.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
25982	Panel - Monitor - Convenience Center	1.00	84.99	84.99

Subtotal for Job #4: 169.99**Job #5 - Warranty**

COMPLAINT: THE BLACK TANK FLUSH IS NOT WORKING.

CAUSE: no water to black tank flush

CORRECTION: took line off to vaccum breaker and i have water coming through breaker, will half to check line to tank. cut several place on underbelly to find water line, found water line in basement area, took off wall to get to line, cut line and turned on water and i could hear air and a little bit of water, cut other side of line where it was spliced in and finally got water, looked in line and found screw where line was spliced. spliced line back together and turned on water and now it works, put wall back in place, covered holes in underbelly and installed screws back in and tied up breaker vacuum.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	255.00

Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	21.99	21.99
88-9504	UNION CONNECTOR 1/2"CST	1.00	7.99	7.99



Subtotal for Job #5: 284.98

Parts Total: 189.96
Labour Total: 680.00
Sublet Total: 0.00
Extras Total: 11.80

WORK ORDER TOTAL: 881.76

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Dec 2024

W/O: 75264
Promised Date: 30 NOV 24



Customer #: 55093
MCCOMBS, DARREN

