



Warranty Authorization Form

Date: 12/20/2024

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 81287 Unit: 7M5FA2821SA009937
Series: Avenue Model: 2025AVE23ML
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22677 VENT - NON POWERED - REPAIR (Photos required) *Fault Code:* PART MISSING

Serial #: *Model #:* *Notes:* 12/20 Jonathan - Per unit photos this is missing and should be installed. 12/17 Jonathan - I'm having a hard time understanding so is there a picture of no vent installed in order to validate this request?

Problem: there is no furnace vent in the bedroom per alliance RUNS UP TO BEDROOM WALL FROM THE BATHROOM UNDER THE VANITY THEN STOPS

Time Requested: .3

Cause: drill hole in the wall in the bedroom from the bathroom to mount a furnace exit in to the bedroom

Time Allowed: .3

Sublet Repairs: 0.00

Remedy: i first removed the hose going into the wall from the bathroom i then got 4 inch hole saw and drilled out the center pont then came to the bedroom and drilled the rest of the hose out then got the hose ran through the wall and got the hole cover and mounted into place

Part Return Req: No

Status: Approved