



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75663
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75663 (Appointment Date: 07 DEC 2024 - Time: 10:00am)

Customer: 9905 - ELLISON, MICHAEL -
812-598-6710

Tag:

Author: BJW

Location: 1219 RO DONE NEED FINAL

Stock #: 11345

Stock Desc: 2024 TT COACHMEN

CATALINA 263BHCKLE

Chassis #: 5ZT2CARB8RX030716

Serial #: 5ZT2CARB8RX030716

Mileage:

Licence:

Invoice #: 412820

Date In: 07 DEC 24

Promised: 31 DEC 24

Date Sched:

Completed: 19 DEC 24

Warr. Date: 29 FEB 24

Job #ALLSEAL - External

COMPLAINT: COMPLETE SEAL INSPECTION. ROOF AND SIDEWALLS. INCLUDES 1 TUBE EACH OF ROOF SEALANT AND SIDEWALL SEALANT.

CAUSE: inspect all seals on unit roof, slide seals, and all exterior seals

CORRECTION: i first got onto roof ad found that there was no soft spots in the roof and there was nothing to seal on the dicor he only thing i would recommend is getting a roof clean and uv protective coating just to futher insure the quality of the roof then inspected every window and seal on the exterior of the nit and found only a few spots that needed touched up and i cleaned and sealed those areas i then ran slide room out and inspected the seals, all the seals are in good condition i then raied seal saver on the wiper sels and slide lubricant on the motor track under the slide

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JG | N/C |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JG | N/C |

Parts

| Part # | Description | Qty | Price | Total |
|---------|-------------------------------------|------|-------|-------|
| 500627 | CLEAR SIKASIL PLUS | 1.00 | N/C | N/C |
| 13-1320 | PW HAPS FREE SELF-LEVELING DICOR | 1.00 | N/C | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|---------------|------|-------|-------|
| SS | SHOP SUPPLIES | 1.00 | N/C | N/C |

Subtotal for Job #ALLSEAL: 0.00

Job #1 - Warranty

COMPLAINT: REAR AWNING ARM NOT CLOSING ALL THE WAY

CAUSE: Rear awning arm not closing all the way

CORRECTION: I first ran awning out to loosen the bolts to move the arm over towards the back of unit to allow it to close properly I then tightened up bolts and ran the awning back in and it is now closing properly

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JG | 51.00 |

Customer #: 9905
ELLISON, MICHAEL



Subtotal for Job #1: 51.00

Job #2 - Warranty

COMPLAINT: CHECK BATTERY...CUSTOMER SAYS IS GOING DEAD WITH SOLAR CHARGER

CAUSE: Battery not charging on solar

CORRECTION: I inspected battery and then found the pannel for the solar and it was not turned on I then turned it on and the battery was at 11.6 then after moving it right outside the door it went up to 12 volts

Labor

| Code | Description | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JG | 34.00 |

Subtotal for Job #2: 34.00

Parts Total: 0.00
 Labour Total: 85.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 85.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Dec 2024

W/O: 75663
Promised Date: 31 DEC 24



Customer #: 9905
ELLISON, MICHAEL

