



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75681
Promised Date: 24 DEC 24



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 75681

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0120 CHECK PREAUTH

Stock #: 11520
Stock Desc: 2025 TT COACHMEN APEX
NANO 208BHS
Chassis #: 5ZT2CXKB5SL018503
Serial #: 5ZT2CXKB5SL018503
Mileage: 0
Licence:

Invoice #:
Date In: 11 DEC 24
Promised: 31 DEC 24
Date Sched:
Completed: 17 JAN 25
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*75771 on 03 JAN 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

Transferred to BAS*75771 on 03 JAN 25
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THE WINDOW BLIND OVER THE KITCHEN SINK IS MISSING A ROD

CAUSE: Missing blind rod

CORRECTION: Installed new rod.

Labor



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Parts				
Part #	Description	Qty	Price	Total
A303	A303 MINI BLIND WAND	1.00	3.51	3.51
Subtotal for Job #1:				3.51

Job #2 - Warranty

COMPLAINT: THE CURTAIN HOLDBACK ON THE UPPER BUNK IS TUCKED UNDER THE TRIM AND STAPLED DOWN.

CAUSE: Strap stuck behind trim

CORRECTION: Removed trim and seen strap had been glued down. Strap is black material with yellow gold stitching and velcro ends. Strap measured 16 in long by 3 in tall.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00

Parts				
Part #	Description	Qty	Price	Total
10353	ASCOT PART# CAX21NP3157 ONYX TIEBACK	1.00	1.14	1.14

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-TIEBACK	1.00	18.36	18.36
Subtotal for Job #2:				36.50

Parts Total:	4.65
Labour Total:	17.00
Sublet Total:	0.00
Extras Total:	18.36
WORK ORDER TOTAL:	40.01

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 Jan 2025

W/O: 75681
Promised Date: 31 DEC 24



Customer #: 1000
BASDEN'S AMERICAN RV,

