



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 75700

### CUSTOMER WORK ORDER

WO #: 75700 (Appointment Date: 13 DEC 2024 - Time: 08:30am)

Customer: 55455 - BUGHER, DAN -

Tag:

Author: BH

Location: 1220 CHECK WORK

Stock #:

Stock Desc: 2025 C COACHMAN

GALLERIA 24QM

Chassis #:

Serial #: W1X8ND3Y1PT142590

Mileage: 2286

Licence:

Invoice #:

Date In: 13 DEC 24

Promised:

Date Sched:

Completed: 17 DEC 24

Warr. Date:

#### Job #1 - Warranty

COMPLAINT: CHECK THE CHASSIS BATTERY CUSTOMER STARTED AT 12/6 WITH 13V 12/7 TRIED TO START AND DIDNT 12/8 12.6---12/9 12.412/10 12.3 1211 STARTED AND DROVE 12/12 12.3 BATTERY IS SLOWLY GOING DOWN MIGHT HAVE AN INTERNAL DRAW IN THE CAMPER

CAUSE: Located battery. Removed trim and floor mat. Removed positive and negative posts. Battery tester is showing a surface charge. Hooked up a water pump and drained voltage. Hooked up the tester. Battery tested at 525 CCA and is rated for 850. Battery needs replaced.

CORRECTION: .

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	170.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

#### Parts

Part #	Description	Qty	Price	Total
10260	MERCEDES BATTERY	1.00	326.03	326.03

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

**Subtotal for Job #1: 581.03**

#### Job #2 - Warranty

COMPLAINT: CHECK THE MASSARATOR IS NOT WORKING RIGHT

CAUSE: PULLED UNIT UP ONTO RAMPS. FLUSHED TANK AND PUMP. CHECKED WIRING LEADING TO PUMP. CHECKED FUSE. REMOVED SWITCH FROM PANEL. CHECKED SWITCH. TESTED FOR POWER LEADING TO SWITCH. 8 VOLTS DC GOING THROUGH WIRE. WENT BACK INSIDE AND PULLED FUSE. FUSE WAS BLOWN BUT WAS MAKING ENOUGH CONTACT INTERNALLY TO NOT FAIL CONTINUTY TEST. REPLAED FUSE. INSTALLED SWITCH. PUMP FUNCTIONS. RAN AND FLUSHED TANK AND PUMP. CLEANED UP AREA.

CORRECTION: .

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	42.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	85.00



Customer #: 55455  
BUGHER, DAN



Subtotal for Job #2: 127.50

W/O: 75700

Parts Total:	326.03
Labour Total:	382.50
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>708.53</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 17 Dec 2024

Customer Signature : \_\_\_\_\_



Customer #: 55455  
BUGHER, DAN

