



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75805
Promised Date:
24 JAN 25

CUSTOMER WORK ORDER

WO #: 75805

Customer: 55496 - CURRY, DAVIE JOHN
PAUL - 386-337-5454

Tag:

Author: DWS

Location: DELIVERY 0131

Stock #: 11412

Stock Desc: 2024 TT COACHMEN

FREEDOM EXPRESS 298FDS

Chassis #: 5ZT2FEVB0RW029702

Serial #: 5ZT2FEVB0RW029702

Mileage:

Licence:

Invoice #:

Date In: 14 JAN 25

Promised: 31 JAN 25

Date Sched:

Completed: 31 JAN 25

Warr. Date: 31 JAN 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi new unit

CORRECTION: I first pulled unit inside and hooked to water then turned on water heater on electric and I turned on both refrigerators then made sure all lights, outlets, and switches worked then did lp drop test and turned on furnace and water heater on gas then did lp drop test and found there was a leak in the lp regulator so I replaced and it stopped the leak then found that the battery terminal to the battery from the solar was to short and i had to make it longer i then made sure there were no visible things needing repairs then winterized and put monster seal in all four tires

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JG	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JG	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JG	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JG	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: i first turned valves on water heater then on the pump and ran antifreeze through all lines then made sure all holding tanks were empty

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JG	N/C

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 55496
CURRY, DAVIE JOHN PAUL





24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
-------	---------------------------	------	-----	-----

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: Install hitch work

CORRECTION: I first removed from box and got all the bolts needed to put the I brackets on and put on the frame and tightened down

I first got all the bolts for the hitch then when putting the receiver to the truck was a 2 1/2 and needed a fitting to make the hitch fit then made sure the unit was level and made sure the hitch was set to the right high and hooked up the hitch and made sure the unit was level

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C
45408	45408 REDUCER SLEEVE SET	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: Put monster seal in tires

CORRECTION: I first removed all valve stems and let all air out then put 2 pumps of monster seal in each tire and put stems back in and aired up to 80 psi

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Subtotal for Job #MONSTER: 0.00

Job #1 - Internal

COMPLAINT: REMOVE MATTRESS FROM UNIT CUSTOMER WILL BRING ON MATTRESS

CAUSE: Remove and replace mattress

CORRECTION: I removed the new mattress and put a mattress the customer supplied

Labor



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Subtotal for Job #1:	0.00
----------------------	------

Job #2 - Warranty

COMPLAINT: SOLAR NEGATIVE TERMINAL IS TOO SHORT TO CONNECT TO BATTERY

CAUSE: Solar terminal was to short to reach the battery

CORRECTION: I cut off the ring terminal on the negative side of the solar i then added an 8 inch extension to make the wire long enough to reach

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	34.00

Subtotal for Job #2:	34.00
----------------------	-------

Job #3 - Warranty

COMPLAINT: LP WILL NOT HOLD LOOSING PRESSURE

CAUSE: Lp leaking after lp drop test

CORRECTION: I spraied down every line and splitter under unit and around tank hoses then I removed and replaced the lp regulator and did an lp drop test again and found that the leak was no longer present

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	85.00

Parts

Part #	Description	Qty	Price	Total
696405	RECALL REGULATOR KIT W/HOSES - KEYST	1.00	28.75	28.75

Subtotal for Job #3:	113.75
----------------------	--------

Parts Total:	28.75
Labour Total:	119.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	147.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Feb 2025

W/O: 75805
Promised Date: 31 JAN 25



Customer #: 55496
CURRY, DAVIE JOHN PAUL

