



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75808
Promised Date:
24 JAN 25

CUSTOMER WORK ORDER

WO #: 75808

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: DWS
Location: 0122 BH TO CLOSE

Stock #: 11536
Stock Desc: 2025 TT COACHMEN APEX
242BARV
Chassis #: 5ZT2CXNB0SS048414
Serial #: 5ZT2CXNB0SS048414
Mileage: 0
Licence:

Invoice #:
Date In: 14 JAN 25
Promised: 31 JAN 25
Date Sched:
Completed: 22 JAN 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CORRECTION: DID PDI PROCESS AND INSPECTION. GOT JOBS FOR ANYTHING I FOUND WRONG.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C
LP20	20 LB. LP CYLINDER	2.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: WINTERIZED UNIT AND DRAINED TANKS. USED 2 GAL OF ANTIFREEZE.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: BATHROOM DOOR HITTING FRAME

CORRECTION: I ADJUSTED THE DOOR HINGES AND CHANGED THE MOUNTING POINTS FOR THE HINGES. I HAD TO MOVE THE DOOR AWAY FROM THE 1/4 ROUND IN THE DOOR JAM. NOW THE DOOR CLOSES AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: WATER LEAKING BETWEEN AWNING RAIL

CORRECTION: WHEN I PULLED THE CAMPER IN THE SHOP, I SEEN THAT WATER WAS LEAKING FROM THE SEAM IN THE GUTTER. I SEALED THE GUTTER FROM THE TOP AND BOTTOM TO PREVENT IT FROM LEAKING AGAIN.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: OUTDOOR ENTERTAINMENT DOOR MISSING INSERT TRIM ON FRONT

CORRECTION: I FOUND THAT THET FRONT SIDE OF THE OUTSIDE ENTERTAINMENT WINDOW / DOOR WAS MISSING THE FRONT TRIM INSERT. I ORDERED A NEW INSERT AND INSTALLED IT WHEN IT GOT HERE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	17.00

Parts

Part #	Description	Qty	Price	Total
15-0395	Used For Doors/ Trim Molding And Win	1.00	1.98	1.98

Subtotal for Job #3: 18.98

Job #4 - Warranty

COMPLAINT: OUTDOOR ENTERTAINMENT DOOR SCREEN HITS SHOCK MOUNTS WIL NOT CLOSE

CORRECTION: I SHAVED DOWN THE SHOCK MOUNT ABOUT 1/8 INCH ON BOTH SIDES. NOW THE SCREEN OPENS AND CLOSES AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00

Subtotal for Job #4: 34.00

Job #5 - Warranty

COMPLAINT: WINDOW STYLE THAT HOLDS SUNSHADE STRING IS SPLIT IN BAR AREA RIGHT SIDE

CORRECTION: I REMOVED THE TRIM FROM THE SIDE OF THE WINDOW AND CUT A NEW 3/4 X 3/4 INCH BOARD TO REPLACE THE ONE THAT WAS SPLIT. I REMOVED THE BAD BOARD FROM THE TRIM AND INSTALLED THE NEW ONE. I PREDRILLED THE HOLES TO KEEP IT FROM SPLITTING AGAIN ON INSTALL. I REINSTALLED THE TRIM AND THEN TIGHTED THE BLIND AFTER

W/O: 75808
Promised Date: 31 JAN 25



Customer #: 1000
BASDEN'S AMERICAN RV,



REINSTALLING THE STRINGS TO THE MOUNTED TRIM.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	85.00
Subtotal for Job #5:			85.00

Job #6 - Warranty

COMPLAINT: BEDROOM SLIDING DOOR NOT MOVING

CORRECTION: I ADJUSTED THE ROLLERS AT THE TOP THE THE DOOR SO THAT IT WAS NOT SETTING ON THE LOWER KEEPER.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Subtotal for Job #6:			34.00

Job #7 - Warranty

COMPLAINT: GALLY TANK DRAIN WILL NOT HOOK UP TO SEWER

CORRECTION: I FOUND THAT THE GALLEY TANK SEWER HOOKUP WAS MOUNTED HIGHER THEN THE J-WRAP. I FOUND THAT I COULD FLIP OVER THE SEWER FITTING TO CLEAR THE J-WRAP. SO I UNBOLTED THE FITTING FROM THE VALVE AND FLIPPED THE SEWER PIPE OVER. NOW THE SEWER HOOKUP FITS WITHOUT HAVING THE J-WRAP IN THE WAY.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00
Subtotal for Job #7:			51.00

Job #8 - Warranty

COMPLAINT: NEED TO RELOCATE THE LP HOOK UP TO OUTSIDE GRILL

CORRECTION: I FOUND THAT THE LP HOSE FOR THE OUT SIDE GRILL WOULD NOT REACH THE PORT UNDER THE UNIT. I WAS ABLE TO UNBOLT THE LP HOSE. I STRAIGHTENED THE LP HOSE AND MOVED THE PORT BACK ON THE FRAME. NOW THE GRILL IS IN LINE WITH THE PORT. I WAS ABLE TO TEST THE GRILL AND PORT. IS WORKS AS IT SHOULD.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	85.00
Subtotal for Job #8:			85.00

Job #9 - Warranty

COMPLAINT: BLACK TANK FLUSHER MISSING RUBBER

CORRECTION: INSTALLED A NEW GROMMET IN THE BLACK TANK FLUSH PORT.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	51.00

Parts				
Part #	Description	Qty	Price	Total
10-1211	20183 3-PK 1" HOSE FILTERS	1.00	2.12	2.12

W/O: 75808
Promised Date: 31 JAN 25



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #9: 53.12

Job #10 - Warranty

COMPLAINT: THE ENTRY DOOR IS OUT OF ADJUSTMENT

CORRECTION: I FOUND THAT THE MAIN DOOR WOULD NOT SHUT WITHOUT PUSHING VERY HARD. I COULD NOT CLOSE THE DOOR AND GET IT TO LATCH FROM THE INSIDE. I TRIED TO ADJUST THE DOOR IT SELF. I THEN ADJUSTED THE STRICKER AND NOW THE DOOR WILL LATCH.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	51.00

Subtotal for Job #10: 51.00

Parts Total: 4.10
 Labour Total: 476.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 480.10

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Jan 2025

W/O: 75808
Promised Date: 31 JAN 25



Customer #: 1000
BASDEN'S AMERICAN RV,

