



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 75861  
Promised Date:  
24 JAN 25

**CUSTOMER WORK ORDER**

WO #: 75861

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: PH  
Location: 0205 BH TO CLOSE

Stock #: 11545  
Stock Desc: 2025 TT COACHMEN APEX  
251RBK  
Chassis #: 5ZT2CXPB6SS048592  
Serial #: 5ZT2CXPB6SS048592  
Mileage: 0  
Licence:

Invoice #:  
Date In: 27 JAN 25  
Promised: 31 JAN 25  
Date Sched:  
Completed: 05 FEB 25  
Warr. Date:



**Job #PDINTT - Internal**

Transferred to BAS\*75905 on 04 FEB 25  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

**Labor**

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

**Job #1 - Warranty**

COMPLAINT: EMERGENCY EXIT SCREEN IS TORN

CAUSE: emergency screen is torn

CORRECTION: took pics and took out and rescreened screen and reinstalled back in place.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

**Subtotal for Job #1: 34.00**

**Job #WINTER - Internal**

COMPLAINT: Transferred to BAS\*75905 on 04 FEB 25  
Estimate amount was 0.00  
WINTERIZE UNIT AND DRAIN HOLDING TANKS.

Customer #: 1000  
BASDEN'S AMERICAN RV,



\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*  
 UNITS WITH WASHING MACHINE OR ICEMAKER  
 WILL BE EXTRA  
 \*\*DE-WINTERIZATION IS NOT INCLUDED\*\*  
 NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: winterize

CORRECTION: winterized unit and did everything on sheet.

<b>Labor</b>				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		DGH	N/C
<b>Other Services</b>				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
<b>Subtotal for Job #WINTER:</b>				<b>0.00</b>

**Job #2 - Warranty**

COMPLAINT: BATHROOM DOOR HITTING FRAME

CAUSE: bathroom door hitting plastic at bottom

CORRECTION: plastic was bowed out at bottom, took off and cut bottom of plastic and reinstalled, door does not hit now.

<b>Labor</b>				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	34.00
<b>Subtotal for Job #2:</b>				<b>34.00</b>

**Job #3 - Warranty**

COMPLAINT: OUTSIDE GRILL IS MOUNTED BACKWARDS

CAUSE: grill hose will not reach hookup

CORRECTION: tried to turn grill the other way but holes don't line up and it will not close, turned back the original way, need to get longer hose.

<b>Labor</b>				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	42.50
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	0.00
<b>Parts</b>				
Part #	Description	Qty	Price	Total
57282	Quick Connect To Quick Connect; With	1.00	37.35	37.35
<b>Subtotal for Job #3:</b>				<b>79.85</b>

**Job #4 - Warranty**

COMPLAINT: SCREWS IN FRONT OF ROCK GUARD ARE COMING OUT

CAUSE: screws came out of wood

CORRECTION: reinstalled screws in wood.

<b>Labor</b>				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DGH	17.00

W/O: 75861  
 Promised Date: 31 JAN 25



Customer #: 1000  
 BASDEN'S AMERICAN RV,



W/O: 75861  
Promised Date: 31 JAN 25



Customer #: 1000  
BASDEN'S AMERICAN RV,



Subtotal for Job #4: 17.00

**Job #5 - Warranty**

COMPLAINT: LEFT REAR WHEEL CENTER CAP FELL OFF

CAUSE: hub cover fell off

CORRECTION: took off wheel and reinstalled cap put wheel back on and retorqued.

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	8.50
<b>Subtotal for Job #5:</b>			<b>8.50</b>

**Job #6 - Warranty**

COMPLAINT: RIGHT FRONT WHEEL HAS NOT BRAKES WIRE IS CUT IN THE AXLE

CAUSE: right front brake dont work

CORRECTION: wire was broke off in axle, tried to fish out wire and no luck ,so pulled out wire on other side and ran across of axle and tied up and connected wires ,tested and it works fine.

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	51.00
<b>Subtotal for Job #6:</b>			<b>51.00</b>

**Job #7 - Warranty**

COMPLAINT: FREEZER BRACKITS ARE BROKEN INSIDE

CAUSE: broken brackets for freezer shelf

CORRECTION: took pics and filled out sheet for parts.

<b>Labor</b>				
Code	Description	Mechanic	Total	
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	3.40	
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	13.60	
<b>Parts</b>				
Part #	Description	Qty	Price	Total
709497	Refrigerator - Shelf Retainer Kit -	2.00	2.77	5.54
<b>Other Services</b>				
Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	19.78	19.78
<b>Subtotal for Job #7:</b>			<b>42.32</b>	

**Job #8 - Warranty**

COMPLAINT: THE FURNACE WILL NOT COME ON

CAUSE: furnance will not kick on.

CORRECTION: took off cushions and unscrewed board and took off cover and found switch was off, turned on and it works, reinstalled board and secured and installed cushions.

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00



**Subtotal for Job #8: 34.00**

Parts Total: 42.89  
Labour Total: 238.00  
Sublet Total: 0.00  
Extras Total: 19.78

**WORK ORDER TOTAL: 300.67**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 05 Feb 2025

W/O: 75861  
Promised Date: 31 JAN 25



Customer #: 1000  
BASDEN'S AMERICAN RV,

