



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75867
Promised Date:
24 JAN 25

CUSTOMER WORK ORDER

WO #: 75867

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: PH
Location: 0210 CHECK PREAUTH

Stock #: 11541
Stock Desc: 2025 TT COACHMEN
FREEDOM EXPRESS 247SE
Chassis #: 5ZT2FEPB2SW030689
Serial #: 5ZT2FEPB2SW030689
Mileage: 0
Licence:

Invoice #:
Date In: 28 JAN 25
Promised: 31 JAN 25
Date Sched:
Completed: 07 FEB 25
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*75906 on 04 FEB 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: STAIN ON CEILING NEXT TO SPEAKER

CAUSE: Pinkish spot on ceiling by speaker...

CORRECTION: Attempted to clean it but wouldn't remove so I used white paint marker to cover it.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	34.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: PANEL UNDER BED IS LOOSE

CAUSE: Loose panel under bed area...

CORRECTION: Stapled panel into place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00

Customer #: 1000
BASDENS AMERICAN RV,



Subtotal for Job #2: 17.00

Job #WINTER - Internal

Transferred to BAS*75906 on 04 FEB 25

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #3 - Warranty

COMPLAINT: THE SHOWER LINER IS NOT COMPLETELY SEALED ON ALL SIDES

CAUSE: Shower liner not sealed...

CORRECTION: Used white silicone to seal right side of shower liner. Due to the liners flex between the mount screws creating a bulge i had to apply pressure while sealing and take down to pull liner closer to wall so silicone could seal.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	34.00

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	18.23	18.23

Subtotal for Job #3: 52.23

Job #4 - Warranty

COMPLAINT: THE SEAM TAPE UNDER THE EMERGENCY EXIT WINDOW IN THE BEDROOM IS
 FLAWED

CAUSE: Loose/Rippled seam tape..

CORRECTION: Applied adhesive and stretched out to remove ripples and make tightened.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00

Subtotal for Job #4: 17.00

Job #5 - Warranty

COMPLAINT: THERE IS A WATER STAIN ON THE CEILING ABOVE THE EMERGENCY EXIT IN THE
 BEDROOM

CAUSE: Stain on wall by ceiling in bedroom.

CORRECTION: Attempted to clean water mark but wouldn't remove so I covered stain with white paint
 marker lightly. Applied all 2nd layer. Checked in roof and found no poor sealed areas.





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00
Subtotal for Job #5:			17.00

Job #6 - Warranty

COMPLAINT: THE LATCH ON THE DRAWER NEAR THE BED IN THE BEDROOM DID NOT HAVE BOTH SIDES OF THE LATH ATTACHED PROPERLY FROM MANUFACTURING

CAUSE: Drawer next to bed didn't have locking latch installed properly...

CORRECTION: Installed the locking mechanism with 2 screws.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	17.00
Subtotal for Job #6:			17.00

Job #7 - Warranty

COMPLAINT: THE CABINET NEXT TO THE COUCH IS CRACKED AND FLAWED

CAUSE: Cracked piece of trim and discolor on wall...

CORRECTION: Doctored the broken area and matched color of wax puddly to cover.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	34.00
Subtotal for Job #7:			34.00

Parts Total:	18.23
Labour Total:	170.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	188.23

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 Feb 2025

