

**e-Authorization**

2/14/20  
05:02:33

3-Authorization number PA03806206 Reference no: 75911 Status: Approved Approved by hull Retail sold on Approved date 2/6/2025  
 rving Name Address VIN

34 Basden's American RV Basden's American RV 4YDTSSGM2XR7103312 6/21/2024  
 600 E Baseline Rd  
 Evansville, IN 47725

Id	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2200515A	Roof Termination	0.00	0.50	0.50		1	0.20	Complaint:DAMAGE NOTES CAMPER IS LEAKING IN THE FRONT WHERE THE BED IS AND AND CUSTOMER FOUND IT ON THE SHELF. AREAS MARKED WITH BLUE TAPE FOUND WATER ON UPPER AND LOWER SHELVES. Cause:water coming in on pas side front. Correction:got on roof and found front transition piece was cracked open had voids in dicor,took pics and filled voids with dicor,and filled voids on side with black silicone.
2	3100208B	Base Cabinets - F	0.00	4.00	2.00		1	0.20	Complaint:CHECK VARNISH COMING OFF BEDSIDE TABLE TOP FROM LEAK Cause:water damage Correction:water damage from leak on roof,put in parts request for paneling.
					2.50				

3-Authorization number PA03806206

paper claims ~~only~~ use one pre-authorization number per warranty claim for  
 ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
 m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the