



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75911
Promised Date: 14 FEB 25

CUSTOMER WORK ORDER

WO #: 75911 (Appointment Date: 05 FEB 2025 - Time: 09:00am)

Customer: 27925 - TAYLOR, BRIAN -
812-480-0588

Tag:

Author: BH

Location: 0220 CHECK STATUS WITH
JRK

Stock #: 11357

Stock Desc: (11357) 2024 KEYSTONE
SPRINGDALE 261BHC

Chassis #: 4YDTSGM2XR7103312

Serial #: 4YDTSGM2XR7103312

Mileage:

Licence:

Invoice #:

Date In: 05 FEB 25

Promised: 14 FEB 25

Date Sched:

Completed: 14 FEB 25

Warr. Date: 21 JUN 24

Job #DAMAGE - Warranty

COMPLAINT: DAMAGE NOTES CAMPER IS LEAKING IN THE FRONT WHERE THE BED IS AND AND CUSTOMER FOUND IT ON THE SHELF. AREAS MARKED WITH BLUE TAPE FOUND WATER ON UPPER AND LOWER SHELVES.

CAUSE: water coming in on pas side front.

CORRECTION: got on roof and found front transition piece was cracked open had voids in dicor,took pics and filled voids with dicor,and filled voids on side with black silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	13.60
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	71.40

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #DAMAGE: 85.00

Job #2 - External

CUSTOMER JUST BOUGHT

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: USB PORTS BY KITCHEN TABLE DOES NOT WORK, MARKED WITH BLUE TAPE

CAUSE: usb dont work

CORRECTION: checked usb with tester and it works fine on both sides and took out to check wires and they are tight,put back in wall and secured,also customers awning was rolled up backwards,i rolled it it up the right way,all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #3: 0.00

Job #1 - Warranty

COMPLAINT: CHECK VARNISH COMING OFF BEDSIDE TABLE TOP FROM LEAK

CAUSE: water damage



Customer #: 27925
TAYLOR, BRIAN



CORRECTION: water damage from leak on roof, put in parts request for paneling.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	340.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
10579	Panel - 3.6mm x 48" x 96" - Carb 2 -	1.00	45.64	45.64

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - PANEL	1.00	159.96	159.96

Subtotal for Job #1: 545.60

Parts Total: 45.64
Labour Total: 425.00
Sublet Total: 0.00
Extras Total: 159.96

WORK ORDER TOTAL: 630.60

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Feb 2025

W/O: 75911
Promised Date: 14 FEB 25



Customer #: 27925
TAYLOR, BRIAN

