



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75929
Promised Date:
13 FEB 25



Customer #: 38487
Merkley, Timothy



CUSTOMER WORK ORDER

WO #: 75929

Customer: 38487 - MERKLEY, TIMOTHY
- 812-306-4445

Tag:

Author: BH

Location: DELIVERY 0213

Stock #: 11421

Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 240RB

Chassis #: 4YDTSG23S7100114

Serial #: 4YDTSG23S7100114

Mileage:

Licence:

Invoice #:

Date In: 08 FEB 25

Promised: 13 FEB 25

Date Sched:

Completed: 24 FEB 25

Warr. Date: 13 FEB 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Pdi Final...

CORRECTION: Preformed the Final inspection and filled out checksheet.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit...

CORRECTION: Winterized unit.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00





Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: New hitch setup

CORRECTION: Opened EQUALIZER HITCH and installed Link Plates at 29in from Ball Mount. Leveled the camper then setup the hitchwork and adjusted as necessary. Tightened all hardware and connected the safety chains, breakaway cable.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #1 - Internal

WASHBAY MAXX GAURD

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: RESEAL THE ROOF

CAUSE: Voids in sealant on roof...

CORRECTION: Filled voids with self leveling dicor. Used 2 tubes.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JRK	51.00
Z990	MISCELLANEOUS REPAIR	JRK	0.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	2.00	7.33	14.66

Subtotal for Job #2: 65.66

Parts Total: 14.66
 Labour Total: 51.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 65.66

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

