

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75948
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 11523 - 2026 FREELANDER 27QB 1FDWE3FN9SDD30100

VIN: 1FDWE3FN9SDD30100 HIN: SER#: 1FDWE3FN9SDD30100

Mileage: 371

Work Order Comp: 28 FEB 25

Auth. No:

Dealer #:

Warr. Date: 05 MAR 25

Work Order Date: 10 FEB 25

Inv #: 414798

WO # Job # Description JOB INFORMATION

75948	3	GREY TANK HEAT PAD FELL OFF grey tank pad fell off took pics and filled out sheet for new pad. I HAD TO SCRAP ALL OF THE GLUE OFF THE TANK AND CLEAN THE BOTTOM OF THE TANK SO THAT THE NEW HEATING PAD WOULD STAY ON. AFTER CLEANING THE TANK, TO TREATED THE TANK WITH 3M PROMOTER. I PUT THE NEW TANK HEATER ON AND TESTED. EVERYTHING IS WORKING AS IT SHOULD.
75948	5	MISSING LENS CAP ON CEILING LIGHT FOUND THAT THE LENS CAP ON 1 LIGHT WAS MISSING ORDERED A LIGHT AND REPLACED IT WHEN IT SHOWED UP.
75948	1	CAP USP PORTS DONT WORK Found that there isn't a charge coming from the usb ports due to a loose wire not connected properly Check cap USB Restored proper connection to the usb ports by putting the wire into the connector and now the usb ports work as originally intended Found that the front cap lights need to be on to power the bunk USB to work.
75948	2	BED COMPARTMENT DOOR HINGES ARNT SCREWED IN Found that the bedroom compartment hinges weren't bolted down properly and was causing it to not be able to open properly due the screws not being long enough Installed longer screws into the hinges and now the compartment door is operating properly

Claim : 75948

 WO # Job # Description JOB INFORMATION

75948 4 TIGHTEN THUMB LATCH ON LP DOOR.
 Tighten thumb latches on LP door.
 I tightened the lp door thumb latches and found that they need to
 remain a little loose or they will not turn

 Part No Job# Description PARTS Qty Price Total

 C01281024 3 HEATING PADS, HOLDING TANK | 110 1.00 20.26 20.26
 C01297527 5 LIGHT, LED INTER. SURFACE MNT, FR 1.00 2.77 2.77

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.50 185.00 92.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 3 UPS-HEATINGPAD 1.00 15.41 15.41
 FRT 5 UPS- CEILING LIGHT 1.00 15.41 15.41

Parts Total: 23.03
 Labour Total: 240.50
 Sublet Total: 0.00
 Extras Total: 30.82

>>>> Claim Total: 294.35

Customer Signature: _____

Date: _____