



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75948
Promised Date:
08 FEB 25

CUSTOMER WORK ORDER

WO #: 75948

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:

Author: BH

Location: 0308 CHECK PREAUTH

Stock #: 11523

Stock Desc: 2026 C COACHMEN

FREELANDER 27QB

Chassis #: 1FDWE3FN9SDD30100

Serial #: 1FDWE3FN9SDD30100

Mileage: 371

Licence:

Invoice #:

Date In: 10 FEB 25

Promised: 28 FEB 25

Date Sched:

Completed: 28 FEB 25

Warr. Date: 05 MAR 25

Job #PDINMHC - Internal

COMPLAINT: Transferred to BAS*76099 on 04 MAR 25

Estimate amount was 0.00

PDI - NEW MOTORHOME "C"

CAUSE: pdi

CORRECTION: did pdi and did everything on sheet,also checked lp,water ,electrical,and appliances and found warrenty jobs.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINMHC: 0.00

Job #FPDINMHC - Internal

Transferred to BAS*76099 on 04 MAR 25

Estimate amount was 0.00

FINAL PDI ON NEW MOTORHOME CLASS C

Labor

Code	Description	Mechanic	Total
PDINMHC	PDI - NEW MOTORHOME "C"	GAH	N/C
PDINMHC	PDI - NEW MOTORHOME "C"	GAH	N/C
PDINMHC	PDI - NEW MOTORHOME "C"	GAH	N/C
PDINMHC	PDI - NEW MOTORHOME "C"	GAH	N/C

Subtotal for Job #FPDINMHC: 0.00

Job #MAXX - Internal

Transferred to BAS*76099 on 04 MAR 25

Estimate amount was 0.00

ROOF VENT COVER - INSTALLED EACH 2 VENTS

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Printed On: 3/10/2025 8:25:43AM

© 2025 Integrated Dealer Systems



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,





Z990	INSTALL MAXX AIR VENT	GAH	N/C
Z990	INSTALL MAXX AIR VENT	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #WINTER - Internal

Transferred to BAS*76099 on 04 MAR 25
 Estimate amount was 0.00
 WINTERIZE UNIT AND DRAIN HOLDING TANKS.
 INCLUDES 2 GALLONS OF ANTI-FREEZE
 UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED
 NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: CAP USP PORTS DONT WORK

CAUSE: Found that there isn't a charge coming from the usb ports due to a loose wire not connected properly
 Check cap USB

CORRECTION: Restored proper connection to the usb ports by putting the wire into the connector and now the usb ports work as originally intended
 Found that the front cap lights need to be on to power the bunk USB to work.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00

Subtotal for Job #1: 55.50

Job #2 - Warranty

COMPLAINT: BED COMPARTMENT DOOR HINGES ARNT SCREWED IN

CAUSE: Found that the bedroom compartment hinges weren't bolted down properly and was causing it to not be able to open properly due the screws not being long enough

CORRECTION: Installed longer screws into the hinges and now the compartment door is operating properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	37.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: GREY TANK HEAT PAD FELL OFF



CAUSE: grey tank pad fell off

CORRECTION: took pics and filled out sheet for new pad.

I HAD TO SCRAP ALL OF THE GLUE OFF THE TANK AND CLEAN THE BOTTOM OF THE TANK SO THAT THE NEW HEATING PAD WOULD STAY ON. AFTER CLEANING THE TANK, TO TREATED THE TANK WITH 3M PROMOTER. I PUT THE NEW TANK HEATER ON AND TESTED. EVERYTHING IS WORKING AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	92.50

Parts

Part #	Description	Qty	Price	Total
C01281024	HEATING PADS, HOLDING TANK 110 HAS	1.00	20.26	20.26

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-HEATINGPAD	1.00	15.41	15.41

Subtotal for Job #3: 128.17

Job #4 - Warranty

COMPLAINT: TIGHTEN THUMB LATCH ON LP DOOR.

CAUSE: Tighten thumb latches on LP door.

CORRECTION: I tightened the lp door thumb latches and found that they need to remain a little loose or they will not turn

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	37.00

Subtotal for Job #4: 37.00

Job #5 - Warranty

COMPLAINT: MISSING LENS CAP ON CEILING LIGHT

CAUSE: FOUND THAT THE LENS CAP ON 1 LIGHT WAS MISSING

CORRECTION: ORDERED A LIGHT AND REPLACED IT WHEN IT SHOWED UP.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00

Parts

Part #	Description	Qty	Price	Total
10668	LIGHT, LED INTER. SURFACE MNT, FROST	1.00	2.77	2.77

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- CEILING LIGHT	1.00	15.41	15.41

Subtotal for Job #5: 36.68

Job #6 - Internal

COMPLAINT: CHECK FRESH TANK FILL

W/O: 75948
Promised Date: 28 FEB 25



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



CORRECTION: CHECKED CITY WATER FILL AND IT IS WORKING AS IT SHOULD, NO LEAKS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #6: 0.00

Parts Total: 23.03

Labour Total: 240.50

Sublet Total: 0.00

Extras Total: 30.82

WORK ORDER TOTAL: 294.35

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Mar 2025

W/O: 75948
Promised Date: 28 FEB 25



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

