



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76126
Promised Date:
no MARD 25

CUSTOMER WORK ORDER

WO #: 76126

Customer: 55554 - COLEY, STACEY E. -
812-470-4006

Tag:

Author: BH

Location: 0328 BH TO CLOSE

Stock #: 11445

Stock Desc: 2025 TT FOREST RIVER

CHEROKEE GREY WOLF 27LH

Chassis #: 4X4TCKC27SX164346

Serial #: 4X4TCKC27SX164346

Mileage:

Licence:

Invoice #:

Date In: 15 MAR 25

Promised: 29 MAR 25

Date Sched:

Completed: 29 MAR 25

Warr. Date: 21 FEB 25

Job #1 - Internal

COMPLAINT: Transferred to BAS*76225 on 15 MAR 25

Estimate amount was 0.00

INSTALL EQUALIZER FROM RO 75989 PREBILLED

CAUSE: Install new e 1000

CORRECTION: I first got all parts of hitch and leveled unit then took measurements and set the hitch to the correct height then hooked hitch and made sure it was level

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: Transferred to BAS*76225 on 15 MAR 25

Estimate amount was 0.00

PREBILLED BRAKECONTROLL FOR RO 75989

CAUSE: Customers SUV needs brake control installed.
Need to reset fridge in unit.

CORRECTION: I installed a brake control and hooked up the wiring under the hood. I had to hook up the trailer charge wire and the brake control power wire under the hood.
I was called over to the delivery area because the fridge would not work. I unhooked the battery and unplugged the unit from shore power. Then hooked the battery back up and plugged the unit into shore power. Now the fridge works as it should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #2: 0.00

Job #4 - Warranty

COMPLAINT: MISSING REMOTE FOR FIREPLACE

CAUSE: Get numbers off fire place

CORRECTION: Took off pannel and removed fire place to see the numbers on the back and took pictures



Customer #: 55554
COLEY, STACEY E.