



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76140
Promised Date:
no MVD 25

CUSTOMER WORK ORDER

WO #: 76140

Customer: 46875 - CHUBBY CHOW

FACTORY LLC - 812-455-2400

Tag:

Author: BH

Location: 0320 BH TO CLOSE

Stock #: 11568

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT SERIES 261BH

Chassis #: 5ZT2CARB5SU045648

Serial #: 5ZT2CARB5SU045648

Mileage: 0

Licence:

Invoice #:

Date In: 07 MAR 25

Promised: 29 MAR 25

Date Sched:

Completed: 25 MAR 25

Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi new unit

CORRECTION: I brought unit in and leveled unit then hooked to city water conection and pressurized the system to check for leaks in the put water in fresh tank and made sure the pump works properly then dewatered unit and made sure all tank sensors, water outlets/inlets were working properly and not leaking I then removed lp tanks off the front of unit and took to fill both tanks i then put tanks back on unit and made sure appliances on lp were working properly (water heater, gas range, furnace) then did lp drop test to make sure the regulator was at the right pressure then made sure there were no leaks in the system with a 5 minute hold test then made sure all 120 volt outlets, water heater, microwave, refrigerator, air-conditioner were working properly then made sure all 12 volt power lights, speakers, radio, awning, leveling system, range hood, USB, USB-C outlets were all working properly

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi new unit

CORRECTION: I brought unit in and leveled unit then hooked to city water conection and pressurized the system to check for leaks in the put water in fresh tank and made sure the pump works properly then dewatered unit and made sure all tank sensors, water outlets/inlets were working properly and not leaking I then removed lp tanks off the front of unit and took to fill both tanks i then put tanks back on unit and made sure appliances on lp were working properly (water heater, gas range, furnace) then did lp drop test to make sure the regulator was at the right pressure then made sure there were no leaks in the system with a 5 minute hold test then made sure all 120 volt outlets, water heater, microwave, refrigerator, air-conditioner were working properly then made sure all 12 volt power lights, speakers, radio, awning, leveling system, range hood, USB, USB-C outlets were all working properly

Customer #: 46875
CHUBBY CHOW FACTORY
LLC,





Labor			
Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JG	N/C

Parts				
Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: I first disconnected city water and put into winterize mode and hooked to antifreeze then turned on pump and made sure water heater was off then ran antifreeze through all water lines and made sure all holding tanks including water heater were empty

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JG	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #MAXX - Internal

COMPLAINT: ROOF VENT COVER - INSTALLED EACH

CAUSE: Install maxx air vent cover

CORRECTION: I first took measurements and made sure the mounting brackets were in the correct location then drilled holds for mounting brackets screws then mounted mounting brackets in places and mounted cover to brackets and made sure then vent worked properly

Labor			
Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	JG	N/C
Z990	INSTALL MAXX AIR VENT	JG	N/C

Parts				
Part #	Description	Qty	Price	Total
22-0257	40443 BLK CAMCO VENT COVER	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #1 - Warranty

COMPLAINT: FRIDGE INSIDE NOT CLOSING RIGHT

CAUSE: Inside fridge door will not close all the way because of the door lock being to far down



CORRECTION: I took pictures and got a Phillips head screw driver and loosened the screws holding the door lock i then pushed it up and tightened screws i then made sure the doors would close properly then cleaned mess

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	55.50

Subtotal for Job #1: 55.50

Parts Total: 0.00

Labour Total: 55.50

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 55.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Mar 2025

W/O: 76140
Promised Date: 29 MAR 25



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

