



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76150
Promised Date:
20 APR 25



CUSTOMER WORK ORDER

WO #: 76150

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0514 CHECK STATUS WITH
JRK

Stock #: 11571
Stock Desc: 2025 TT ALLIANCE RV
DELTA 294RK
Chassis #: 7M5TD3322SC305724
Serial #: 7M5TD3322SC305724
Mileage: 0
Licence:

Invoice #:
Date In: 08 MAR 25
Promised: 30 APR 25
Date Sched:
Completed: 10 MAY 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*76681 on 06 MAY 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: Pdi...

CORRECTION: Checked roof. Checked coupling, safety chains, tonguejack, stability jacks, lights, breakaway switch, brakes and dump valves. Checked Tire pressure and lug Torque. Checked all compartment doors. Adjusted steps. Checked awning and awning lights. Dewinterized unit. Lp droptest done. Ran Furnace and water heater. Checked grill. Checked Stovetop. Checked all compartment and drawers. Checked fireplace. Checked AC. Checked fridge. Checked both TVs and Antenna connection. Checked Microwave and it's missing the circulating ring and glass turntable. Checked 120v recepticals and 12v USB ports. Removed packing from appliances. Checked outside grille. Took manufacturer labels pictures and filled out all my paperwork. Installed a battery box. Retracted both Slideouts and Awnings. Wrapped up Shore Power Cord and turned off battery disconnect. Dumped all tanks.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: Transferred to BAS*76681 on 06 MAY 25
Estimate amount was 0.00
TEAR IN THE LINO IN BATHROOM

CAUSE: Dent in linoleum in bathroom floor...

CORRECTION: Looked it over with Brett and he said there isn't much we can do with it outside of a replacement which he didn't recommend for such a minor spot.



Customer #: 1000
BASDEN'S AMERICAN RV,





Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SCRATCH ON CABINET DOOR IN BATHROOM

CAUSE: Scratch on vanity door in bathroom...

CORRECTION: Took pick of scratched area and took measurements... 31in tall, 15in wide and 3/4in thick.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Parts

Part #	Description	Qty	Price	Total
29769	29769 Door - Cab - 15 x 31 w/Mirror	1.00	30.99	30.99

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 2,8	1.00	12.25	12.25

Subtotal for Job #2: 80.24

Job #3 - Warranty

COMPLAINT: 2 LIGHTS ARE LOOSE IN LIVING ROOM

CAUSE: Ceiling Lights not efficiently pushed into ceiling...

CORRECTION: Tightened the spring mechanism that holds lights up.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	18.50

Subtotal for Job #3: 18.50

Job #4 - Warranty

COMPLAINT: STAIN ON COUCH CUSHION

CAUSE: Found a stain on backside of couch...

CORRECTION: Used all soap and water with a soft cloth and removed stain.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Subtotal for Job #4: 37.00

Job #5 - Warranty

COMPLAINT: STAIN ON RECLINER CUSHIONS

CAUSE: Found a few stains on Recliners cushions...

CORRECTION: Used all soap and water and cloth and cleaned stains from cushions.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Subtotal for Job #5: 37.00

Job #6 - Warranty

COMPLAINT: REAR ROOF TRIM PIECE NEEDS RESEALED NEXT TO LADDER

CAUSE: Clean and seal area of roof by ladder...

CORRECTION: Cleaned and filled 2 void areas in rear trim on roof.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	18.50
Subtotal for Job #6:			18.50

Job #7 - Warranty

COMPLAINT: MARKER LIGHT LOOSE

CAUSE: Marker light loose...

CORRECTION: Located and removed cover and tightened screws and reinstalled cover.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00
Subtotal for Job #7:			37.00

Job #8 - Warranty

COMPLAINT: MICROWAVE IS MISSING THE RING AND TURN TABLE

CAUSE: Missing turntable and rotating ring...

CORRECTION: Submitted parts request for both missing parts.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Parts Part #	Description	Qty	Price	Total
26043	26043 Glass Plate - Microwave - Grey	1.00	19.99	19.99
26044	26044 Ring - Turntable - Microwave -	1.00	9.99	9.99

Subtotal for Job #8: 48.48

Job #9 - Warranty

COMPLAINT: SLIDE ROOM DOESNT WORK

CAUSE: Doorside slideout only worked periodically...

CORRECTION: Located the wire connections and found a ground was only partially making connections. Stripped the insulation coating back more to make a solid connection. Test slideout 3 times to verify correction.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	18.50

W/O: 76150
Promised Date: 30 APR 25



Customer #: 1000
BASDENS AMERICAN RV,



Subtotal for Job #9: 74.00

W/O: 76150
Promised Date: 30 APR 25

Parts Total: 60.97
Labour Total: 277.50
Sublet Total: 0.00
Extras Total: 12.25
WORK ORDER TOTAL: 350.72

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 May 2025



Customer #: 1000
BASDEN'S AMERICAN RV,

