

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

Labor rate: \$185.00

OWNER INFORMATION

Retail Date of Purchase

CLAIM STATUS Authorized
CLAIM 2247481
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZTCFLS07TP432864
CHASSIS VIN 1FDWE3FN9SDD30100
MILEAGE 375
SITE/WAREHOUSE 210 / 210
ITEM # FLC27QBF35
DEALER RO #
CLAIM START DATE 03/31/2025
CLAIM END DATE 01/01/1900

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code

40-196-24-11-001297

Operational Description

Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-03-31 10:31:57 :: SOLENOID IS WIRED WRONG IN THE BATTERY AREA We were told by the manufacturer that the yellow wire should be hooked up to the solenoid. This unit has the black wire with a yellow strip hooked up. It should be changed. I hooked up the yellow wire to the solenoid.

Model#

Dlr Sub Hrs

0.10

Sub Labor Amt \$18.50

Serial#

Appr Hrs

0.10

Appr Labor Amt \$18.50

Notes

1) ok nw

Labor

Line# 2

Operation Code

30-92-01-00-001149

Operational Description

Fire Extinguisher - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-03-31 10:33:06 :: CAMPER HAS NO FIRE EXTINGUISHER Unit has no fire extinguisher. I got a fire extinguisher and mounted it to the wall inside the main door.

Model#

Dlr Sub Hrs

0.05

Sub Labor Amt \$9.25

Serial#

Appr Hrs

0.05

Appr Labor Amt \$9.25

Notes

Submitted

Labor Amt \$27.75
Parts & Freight \$0.00
Total \$27.75

Approved

Labor Amt \$27.75
Parts & Freight \$0.00
Total \$27.75

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.