



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76310
Promised Date:
25 APR 25

CUSTOMER WORK ORDER

WO #: 76310 (Appointment Date: 25 MAR 2025 - Time: 02:30pm)

Customer: 54410 - GURDO, JR,
ARTHUR SAMUEL - 618-384-8313

Tag:
Author: DWS
Location: 0415 CHECK STATUS WITH
ZMS

Stock #: 10913
Stock Desc: 2023 TT FOREST RIVER
CHEROKEE WOLF PUP 18TO
Chassis #: 5ZT2CKGC2PY028887
Serial #: 5ZT2CKGC2PY028887
Mileage: 0
Licence:

Invoice #:
Date In: 25 MAR 25
Promised: 30 APR 25
Date Sched:
Completed: 11 APR 25
Warr. Date: 30 APR 24

Job #1 - Warranty

COMPLAINT: OUTSIDE MINI FRIDGE NOT WORKING

CAUSE: Pulled unit up to shop. Opened slide room. Removed mounting bolts hold fridge in place. Removed the fridge from the unit. Plugged the fridge in and turned the t stat all the way up. Came in the next day and the fridge is not cold at all. The compressor is running and is hot. Need approval for replacement fridge.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100077545	REFRIGERATOR - CONTOURE 1.7 CU FT.	1.00	134.55	134.55

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
FRT	SHIPPING-FRIDGE	1.00	175.00	175.00

Subtotal for Job #1: 402.05

Job #2 - Warranty

CHECK DECALS STARTING TO PEEL OFF DOOR SIDE WOLF PUP DECAL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100284955	DECAL, 2022 WOLF PUP METAL UNIT SIDE	1.00	6.34	6.34

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECAL	1.00	15.53	15.53

Subtotal for Job #2: 114.37



Customer #: 54410
GURDO, JR, ARTHUR
SAMUEL



W/O: 76310
Promised Date: 30 APR 25

Job #3 - Warranty

COMPLAINT: STAPLES COMING OUT OF MOLDING OF BED

CAUSE: Trim on bed is loose and has a staple hanging out.

CORRECTION: Removed staples. Secured with Brad rails. Filled holes with putty.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Subtotal for Job #3: 37.00

Parts Total: 140.89
Labour Total: 222.00
Sublet Total: 0.00
Extras Total: 190.53
WORK ORDER TOTAL: 553.42

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 11 Apr 2025

Customer Signature : _____

Customer #: 54410
GURDO, JR, ARTHUR
SAMUEL

