

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76373
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 54471 - ERIC BEASLEY
Address: 1999 E COUNTY ROAD 475 S WINSLOW, IN

47598

Phone: 812-582-1673

Stock Number: 11296 - 2024 DELTA 281BH 7M5TD3129RC302297

VIN: 7M5TD3129RC302297 HIN:

SER#: 7M5TD3129RC302297

Mileage: 0

Work Order Comp: 30 APR 25

Auth. No:

Dealer #:

Warr. Date: 02 MAR 24

Work Order Date: 01 APR 25

Inv #: 416899

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

76373	1	CUSTOMER HAS TANKLESS W/H. EVERYTIME HE TURNS IT ON, IT BLOWS A FUSE Water has a short in the control board Started at the outside of the water heater to see if it was on then tried to put a 15 amp fuse in place and it popped. Went back out to the outside of the water heater and shut it off. Tried to put another 15 amp fuse in and it popped again. Disconnected the positive wire on the water heater. Put the volt meter on the positive wire then to a ground and there was continuity. At the control board on the water heater it smells burnt. Would recommend a new water heater, not sure what else was damaged in the water heater and touch pad.	
76373	2	CUSTOMER ADVISES HE CAN NOT GET THE SPRAY HOSE IN THE SPRAY PORT AT THE BACK OF THE RV. Spray port connection won't hold the hose in the quick connection. Took the spray port hose and put in the quick connection but didn't stay in place. Put in po for a new spray port connection.	
76373	4	THE JWRAP IS SCREWED UNDER AROUND EXECT FOR THE GRILL AREA AND FRIDGE IT IS COMING LOOSE J wrap below the outdoor kitchen is not secured properly. Took pictures of the j wrap not sitting in place. Unscrewed the black trim above the white j wrap that is on both sides of the	

Claim : 76373

 WO # Job # Description JOB INFORMATION

outside kitchen door. Pushed the j wrap up about 1/8 inch then
 put staples in to hold the j wrap up. Screwed the trim back on
 and trimmed with silicone.

 Part No Job# Description PARTS Qty Price Total

 24097 1 Water Heater - Tankless - 2.4gal 0.00 334.99 0.00
 31496 1 Furrion Replacement RV Tankless W 1.00 105.99 105.99
 24404 2 Spray Port - O/S w/Metal MPT Conn 1.00 11.99 11.99

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.70 185.00 129.50
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-CONTROLLER 1.00 11.58 11.58
 FRT 2 UPS-SPRAY PORT 1.00 12.27 12.27

Parts Total: 117.98
 Labour Total: 203.50
 Sublet Total: 0.00
 Extras Total: 23.85

>>>> Claim Total: 345.33

Customer Signature: _____

Date: _____