



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76544
Promised Date:
24 MAY 25

CUSTOMER WORK ORDER

WO #: 76544

Customer: 46875 - CHUBBY CHOW

FACTORY LLC - 812-455-2400

Tag:

Author: BH

Location: 0507 CHECK PREAUTH

Stock #: 11589

Stock Desc: 2025 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG16SW104214

Serial #: 4YDTSGG16SW104214

Mileage: 0

Licence:

Invoice #:

Date In: 21 APR 25

Promised: 31 MAY 25

Date Sched:

Completed: 30 APR 25

Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi new...

CORRECTION: Damaged key hole on entry door, replaced cylinders and took new keys to Chad. Checked roof. Checked cap seals. Checked doors and compartment door. Installed new battery box and 12v battery. Checked and adjusted Tire pressure and lug Torque. Filled LP tank. Hooked up units Shore Power Cord. Filled up Freshtank and Dewinterized unit. Ran LP droptest. Tested all appliances and removed manufacturers packageing. Checked all cabinets doors and drawers. Checked all windows and blinds. Checked 120v recepticals and 12v USB ports. Took all my manufacturer label pictures and filled out checksheet.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C
PARTS	374 KEY CYLINDER (ENTRY DOOR)	2.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Preform pdi final...

CORRECTION: Preformed pdi final and filled out checksheet.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JRK	N/C



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



W/O: 76544
Promised Date: 31 MAY 25



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,



Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #MAXX - Internal

COMPLAINT: ROOF VENT COVER - INSTALLED EACH

CAUSE: Install vent cover...

CORRECTION: Installed Vent cover in roof.

Labor

Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	JRK	N/C

Parts

Part #	Description	Qty	Price	Total
22-0257	40443 BLK CAMCO VENT COVER	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #1 - Warranty

COMPLAINT: BOTTOM BUNK SUPPORT IS BROKEN

CAUSE: Support board under bed not attached...

CORRECTION: Installed support board under bunk.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JRK	72.00

Subtotal for Job #1: 72.00

Parts Total: 0.00
Labour Total: 72.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 72.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 May 2025

