

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76557
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 55742 - CARL WOLFE
Address: 169 CULLEN RD MORGANFIELD, KY

42437

Phone: 270-952-6571

Stock Number: 11582 - 2025 CATALINA SUMMIT SERIES 271DBS 5ZT2CASB2SU046038

VIN: 5ZT2CASB2SU046038 HIN: SER#: 5ZT2CASB2SU046038

Mileage: 0 Work Order Comp: 30 JUN 25

Auth. No: Dealer #:

Warr. Date: 29 APR 25 Work Order Date: 22 APR 25 Inv #: 419473

WO #	Job #	Description	JOB INFORMATION
76557	8	ONE OF THE DECALS IS BROKEN AND NEEDS REPLACED There is a hole in the back of the decal. Need to replace the decal. Black "summit series "	
76557	12	THE FRONT DOOR SIDE JACK IS NOT WORKING. When running the Jack's only one side goes down. Motor started to smoke on the passenger side. Motor is locked up. It will not move on manually either.	
76557	14	DENT ON THE FREEZER DOOR Dent on freezer. Took pictures and filled out parts request.	
76557	5	THE BATHROOM NOT BEDROOM DOOR NEEDS TO BE ADJUSTED Door will not latch. The latch was positioned incorrectly and was bent. Removed the latch and straightened the latch and sanded excess wood where the latch sits. Installed latch. Door latches as it should.	
76557	6	THE TRIM ON THE BIG DOOR OF THE ENTERTAINMENT CENTER IS MISALIGNED Trim is loose. Secured trim with Brad nails	
76557	9	THERE ARE BUBBLES IN THE DECALS ON THE OFF DOOR SIDE Bubbles in decals.	

Claim : 76557

 WO # Job # Description JOB INFORMATION

Popped holes near bubbles and smoothed out with a rag and soapy water

76557 10 THERE ARE BUBBLES IN THE DECAL ON THE DOOR SIDE
 Bubbles in decal
 Popped bubbles and smoothed out with a rag and soapy water.

76557 11 THE FRONT SCREEN NEEDS TO BE ADJUSTED
 Screen door latch isn't holding the door.
 Removed latch. Installed 2 washers to push latch closer to the door.

76557 13 SLIDE SKIS ARE NOT SECURE ON THE SLIDE ROOM
 Slide skis aren't secure to the floor.
 Applied 3m tape to the skis and placed a jack with x 2x6 to support the skis. Removed posts the next morning. Skis are secured.

76557 15 WALL PANEL IS LOOSE IN THE BEDROOM DOOR SIDE
 Panel came loose from the wall stud.
 Secured with staples and filled staple holes with putty.

 Part No Job# Description PARTS Qty Price Total

Part No	Job#	Description	PARTS	Qty	Price	Total
F100597137	8	GRAPHIC, #44 "SUMMIT SERIES" SIDE		1.00	10.57	10.57
F100418468	8	GRAPHIC		1.00	5.14	5.14
F100516332	12	MOTOR ONLY FOR BAL AUTO LEVELING		1.00	91.08	91.08
F100282071	14	GE STAINLESS FREEZER DOOR 2022		1.00	426.94	426.94

 Lab Code Job# Description LABOUR Hrs Rate Total

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	14	MISC LABOUR CODE (EXTERNAL)		0.39	185.00	72.15
Z990	14	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	14	MISC LABOUR CODE (EXTERNAL)		0.01	185.00	1.85
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50

Claim : 76557

```
*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      9   MISC LABOUR CODE (EXTERNAL)      0.50    185.00    92.50
Z990     10   MISC LABOUR CODE (EXTERNAL)      0.30    185.00    55.50
Z990     11   MISC LABOUR CODE (EXTERNAL)      0.20    185.00    37.00
Z990     13   MISC LABOUR CODE (EXTERNAL)      0.38    185.00    70.30
Z990     13   MISC LABOUR CODE (EXTERNAL)      0.11    185.00    20.35
Z990     13   MISC LABOUR CODE (EXTERNAL)      0.01    185.00     1.85
Z990     15   MISC LABOUR CODE (EXTERNAL)      0.20    185.00    37.00
*****
```

```
*****
Excode    Job#  Description          EXTRAS          Qty      Price     Total
*****
FRT       8   UPS-MOTOR&GRAPHIC      1.00     15.51    15.51
FRT       8   UPS-DECAL              1.00     15.65    15.65
FRT      14   SHIPPING-FREEZER DOOR  1.00     10.66    10.66
*****
```

Parts Total: 533.73
Labour Total: 647.50
Sublet Total: 0.00
Extras Total: 41.82

>>>> Claim Total: 1,223.05

Customer Signature: _____

Date: _____