

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 76570  
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
Customer: 55516 - ANDREW HOWARD  
Address: 161 DRIFTWOOD LN  
NEWBURGH, IN  
47630  
Phone: (812) 480-5861  
Stock Number: 11590 - 2025 COUGAR SPORT 2400RE 4YDFCGL26SV506104  
VIN: 4YDFCGL26SV506104 HIN: SER#: 4YDFCGL26SV506104  
Mileage: 0 Work Order Comp: 23 JUL 25  
Auth. No: Dealer #: 1194  
Warr. Date: 25 APR 25 Work Order Date: 23 APR 25 Inv #: 420213

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
76570	4	SCREEN NEXT TO DINNETTE SEAT WONT LATCH Screen won't latch into window. Tried multiple times to reinstall. Request to order a new screen. The screen that came in was the wrong size. Put screen back in box and placed in warranty department. Sent another parts request. 6-13-25.	
76570	7	SCRATCHES ON TABLE Scratches on table in livingroom. We will need to replace the table. Tried to removed scratches but they didn't come out.	
76570	10	LP TANK WILL NOT FILL TANK WONT FILL NEED TO REPLACE REPLACE THE TANK	
76570	1	POSITIVE BATTERY CABLE IS TOO SHORT TO REACH BATTERY BOX 12 volt positive cable is too short. removed cover. removed cable. cut new cable to length. installed wire terminals. secured wire to battery and power distribution box.	
76570	2	DRAWER IN BEDROOM IS COMING LOOSE Drawer face gap Took a hammer and fixed the gap	
76570	3	ENTRY DOOR FRAME IS BENT The entry door frame is bent.	

Claim : 76570

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*

    Took a hammer and 2 blocks of wood to straighten the frame.

76570      5      FIRE PLACE REMOTE WONT WORK

76570      8      BLACK MARKS NEXT TO LIGHT ON CEILING IN LIVING ROOM  
           Black mark on ceiling by light  
           Cleaned ceiling with mineral spirits removed black mark

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
499887	4	Screen - Window - Replacement - A		1.00	18.42	18.42
718319	7	Flip up Table 24 X 39 1/2-Cougar		1.00	42.91	42.91
66-4907	10	L.P.CYLINDER 30 LB. PW		1.00	91.90	91.90

\*\*\*\*\*

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	4	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	4	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	4	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	7	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	7	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	7	MISCELLANEOUS REPAIR		0.20	180.00	36.00
Z990	7	MISCELLANEOUS REPAIR		0.00	180.00	0.00
Z990	10	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	1	MISCELLANEOUS REPAIR		0.20	180.00	36.00
Z990	2	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	3	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	5	MISCELLANEOUS REPAIR		0.10	180.00	18.00
Z990	8	MISCELLANEOUS REPAIR		0.10	180.00	18.00

\*\*\*\*\*

\*\*\*\*\*

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	4	UPS-SCREEN		1.00	31.16	31.16
FRT	7	UPS-TABLE		1.00	73.78	73.78

\*\*\*\*\*

Parts Total:           153.23  
 Labour Total:         180.00  
 Sublet Total:         0.00  
 Extras Total:         104.94

>>>> Claim Total:           438.17

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_