

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76599
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 27089 - ALLEN DUKE
Address: 7954 LYDDANE BRIDGE RD S OWENSBORO, KY

42301

Phone: 270-570-4799

Stock Number: 11579 - 2025 CATALINA SUMMIT SERIES 261BHS 5ZT2CARB1SU045761

VIN: 5ZT2CARB1SU045761 HIN: SER#: 5ZT2CARB1SU045761

Mileage: 0

Work Order Comp: 08 MAY 25

Auth. No:

Dealer #:

Warr. Date: 12 APR 25

Work Order Date: 28 APR 25

Inv #: 417036

WO # Job # Description JOB INFORMATION

76599 2 CUSTOMER ADVISES THAT WATER RUNS DOWN THE SIDE OF THE CAMPER
BETWEEN THE GUTTER AND THE SIDEWALL.
Assess leak at gutters and sidewall...
After looking over gutters system, gutters seams where 2
separate pieces meet aren't sealed properly. One of the gutters
(doorside) also had black dicor built up in gutter at seam which
i cleaned out and sealed the bottom of gutters at seams.

76599 3 THE WALL BY THE DINETTE HAS WALL PAPER THAT WON'T STAY STAY
STUCK DOWN. THE PIECE ON THE WALL BY THE BATHROOM IS LOOSE AND
NOT SECURED
Assess wallpaper by dinette and wall by bathroom...
Area by dinnette was actually a loose wall panel, which i removed
the seam tape and stapled panel back into stud and reapplied seam
tape. The 1.5ft section of wall panel between the bathroom door
and dinnette has a little flimse to it but due to no stud in this
section it can't be reinforced in the middle but all edges are
secured.

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50

Parts Total: 0.00

Labour Total: 92.50

Sublet Total: 0.00

Extras Total: 0.00

>>>> Claim Total: 92.50

Customer Signature: _____

Date: _____

Claim : 76599

```
*****
Lab Code  Job#  Description      LABOUR              Hrs      Rate      Total
*****
```