

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76637
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11591 - 2025 DELTA 262RB 7M5TD2923SC306379
VIN: 7M5TD2923SC306379 HIN: SER#: 7M5TD2923SC306379
Mileage: 0 Work Order Comp: 14 MAY 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 01 MAY 25 Inv #: 417297

WO # Job # Description JOB INFORMATION

76637 1 BATH ROOM FAN NOT WORKING
Bathroom fan and rear camera tide on the same circuit Fan not working
Connected a tone generator to the wires at the bathroom fan and chased down the wire. Found the wire connected to the backup camera switch. When the camera is on the bathroom fan works. Camper has no camera installed. I pulled off the fan to chase the pink and white wire down to the fuse box. Check the fuses all the fuses were good unplugged the pink and wipe cord to chase it down into the ceiling to the fan to come to realize that it was not properly installed. So I installed it correctly and now the fan is working

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.11 185.00 20.35
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.39 185.00 72.15

Parts Total: 0.00
Labour Total: 92.50
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 92.50

Customer Signature: _____

Date: _____