



Warranty Authorization Form

Date: 5/14/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 92799 Unit: 7M5TD2923SC306379
Series: Delta Model: 2025DEL262RB
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 18006 12 VOLT - GENERAL REPAIR

Fault Code: IMPROPERLY INSTALLED

Serial #:

Model #:

Notes:

Problem: BATH ROOM FAN NOT WORKING

Time Requested: .5

Cause: Bathroom fan and rear camera tied on the same circuit Fan not working

Time Allowed: .5

Remedy: Connected a tone generator to the wires at the bathroom fan and chased down the wire. Found the wire connected to the backup camera switch. When the camera is on the bathroom fan works. Camper has no camera installed. I pulled off the fan to chase the pink and white wire down to the fuse box. Check the fuses all the fuses were good unplugged the pink and white cord to chase it down into the ceiling to the fan to come to realize that it was not properly installed. So I installed it correctly and now the fan is working

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved