



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76638
Promised Date:
24 MAY 25

CUSTOMER WORK ORDER

WO #: 76638

Customer: 55833 - MCCORMICK, PAUL -
812-205-5940

Tag:

Author: BH

Location: 0620 CHECK STATUS WITH
BB

Stock #: 11592

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT SERIES 134RKX

Chassis #: 5ZT2CABCXSK011204

Serial #: 5ZT2CABCXSK011204

Mileage: 0

Licence:

Invoice #:

Date In: 01 MAY 25

Promised: 31 MAY 25

Date Sched:

Completed: 11 JUN 25

Warr. Date: 30 MAY 25

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*76919 on 03 JUN 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: PDI NEW

CORRECTION: I brought unit in and leveled unit then hooked to city water conection and pressurized the system to check for leaks in the put water in fresh tank and made sure the pump works properly then dewatered unit and made sure all tank sensors, water outlets/inlets were working properly and not leaking I then removed lp tank off the front of unit and took to fill tank

I then put tanks back on unit and made sure appliances on lp were working properly (water heater, gas range, furnace) then did lp drop test to make sure the regulator was at the right pressure then made sure there were no leaks in the system with a 5 minute hold test then made sure all 120 volt outlets, water heater, microwave, refrigerator, air-conditioner were working properly then made sure all 12 volt power lights, speakers, radio, awning, range hood, USB, outlets were all working properly

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE ENTRY DOOR HITS THE FRAME WHEN CLOSING AND IT DOES NOT CLOSE ALL THE WAY.

CAUSE: Entry door

CORRECTION: When opening and closing the door the frame is rubbing and so I had to readjust the frame and also position of where the latch goes and now the door shuts properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50



Customer #: 55833
MCCORMICK, PAUL



Subtotal for Job #1: 55.50

Job #2 - Warranty

THIS UNIT IS MISSING A 30 AMP SHORE POWER CORD

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00

Parts

Part #	Description	Qty	Price	Total
19-1811	A10-3025ED 30A 25' TWISTLOCK	1.00	70.10	70.10

Subtotal for Job #2: 70.10

Job #3 - Warranty

COMPLAINT: THERE IS A DENT ON THE NOSE CAP.

CAUSE: Dent in nose cap

CORRECTION: When looking at the picture submitted the dent is in the smaller circle the dent isn't noticed until you rub your hand over it and can feel it and see it

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	462.50
Z990	MISC LABOUR CODE (EXTERNAL)	BB	185.00

Parts

Part #	Description	Qty	Price	Total
F100162292	METAL, .040 48 X 96 CTL SL BLACK W/	1.00	120.83	120.83
F100418580	GRAPHIC, #15 DS CATALINA SUMMIT 2024	1.00	1.31	1.31
F100418582	GRAPHIC, #17 FRONT MOUNTAINS CATALIN	1.00	11.03	11.03
F100418581	GRAPHIC, #16 ODS CATALINA SUMMIT 202	1.00	1.31	1.31
F100597115	GRAPHIC, #9 FRONT "CATALINA" 2025 LE	1.00	10.25	10.25
3388	551LSB-1 BLACK NON SAG DICOR	1.00	8.43	8.43
219088	SILICONE II BLACK	1.00	11.99	11.99
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	8.26	8.26
F100359506	SILICONE, NEUTRAL CURE SILICONE 10.3	1.00	12.09	12.09

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-METAL 6-2-25	1.00	437.48	437.48

Subtotal for Job #3: 1,455.48

Job #4 - Internal

COMPLAINT: INSTALL KEYLESS ENTRY DOOR HANDLE

CORRECTION: installed keyless lock

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C



Parts
Part #
8946

Description	Qty	Price	Total
Compact RVLock Keyless Entry Handle	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total: 255.60
Labour Total: 888.00
Sublet Total: 0.00
Extras Total: 437.48
WORK ORDER TOTAL: 1,581.08

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Jun 2025

W/O: 76638
Promised Date: 31 MAY 25



Customer #: 55833
MCCORMICK, PAUL

