

# FOREST RIVER WARRANTY CLAIM FORM

**DEALER ACCOUNT #** 0005106  
 BASDEN RV CENTER INC  
 DBA AMERICAN RV CENTER  
 600 E BASELINE ROAD  
 EVANSVILLE, IN 47725  
 USA

**CLAIM STATUS** Authorized  
**CLAIM** 2303194  
**CLAIM ORIGIN** WEB  
**ORIGINAL CLAIM ID**  
**VIN** 5ZT2CASB3SU044881  
**CHASSIS VIN**  
**MILEAGE** 0  
**SITE/WAREHOUSE** 103 / 103  
**ITEM #** CAT271DBS-8  
**DEALER RO #** 76657  
**CLAIM START DATE** 05/19/2025  
**CLAIM END DATE** 01/01/1900

**Labor rate:** \$185.00

**OWNER INFORMATION**

JONATHAN M WHEELER  
 1400 REITER DR  
 Evansville, IN 47712  
 USA

**Retail Date of Purchase** 05/08/2025

**WARRANTY EXPIRATION DATE**

05/08/2026

**Claim Line Details**

**Labor**

<b>Line#</b> 1	<b>Operation Code</b> 40-106-01-12-001216	<b>Operational Description</b> Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting
	<b>Complaint, Cause, Correction</b>	
	Original Note : bhoffman@americanrvcenter.com, 2025-05-19 10:25:14 :: RIGHT REAR MARKER LIGHT IS HALF FULL OF WATER AND NOT WORKING Right rear marker light 1/2 full of water Replaced right rear marker light that was 1/2 full of water and didn't work. Installed a new marker light and after install it works properly.	
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20	<b>Sub Labor Amt</b> \$37.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.20	<b>Appr Labor Amt</b> \$37.00
	<b>Notes</b>	

<b>Submitted</b>	Labor Amt	\$37.00
	Parts & Freight	\$0.00
	<b>Total</b>	<b>\$37.00</b>

<b>Approved</b>	Labor Amt	\$37.00
	Parts & Freight	\$0.00
	<b>Total</b>	<b>\$37.00</b>

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

All repairs described have been inspected and are satisfactory.