

Pre-Authorization

Pre-Authorization number PA03855258 Reference no: 76665 Status: Approved Approved by kiddz Approved date 5/22/2025
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDFCGR28S2503116 5/17/2025
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6201106B	Regulator - Repla	0.00	0.30	0.50		1	0.30	Complaint:REGULATOR WILL NOT ADJUST Cause:New pdi regulator would not adjust Correction:Upon doing first LP drop test found out that regulator would not adjust. Put in a parts request for a new regulator. Installed new regulator checked outside conditions no leaks have to perform a new drop test to insure working properly and not leaks. System works properly now no leaks
2	6200106A	Drop Pressure Te	0.00	0.30			1	0.20	Complaint:Upon doing first LP drop test found out that regulator would not adjust. Put in a parts request for a new regulator. Installed new regulator checked outside conditions no leaks have to perform a new drop test to insure working properly and not leaks. System works properly now no leaks Cause:Upon doing first LP drop test found out that regulator would not adjust. Put in a parts request for a new regulator. Installed new regulator checked outside conditions no leaks have to perform a new drop test to insure working properly and not leaks. System works properly now no leaks Correction:Upon doing first LP drop test found out that regulator would not adjust. Put in a parts request for a new regulator. Installed new regulator checked outside conditions no leaks have to perform a new drop test to insure working properly and not leaks. System works properly now no leaks

KRV- time on line 1.

Pre-Authorization number PA03855258 0.50

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company