

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2294471
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAMB0SU046102
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT231MKS-8
		DEALER RO #	76666
		CLAIM START DATE	05/10/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-102-36-00-002279	Operational Description Wall Panel - Interior/Panels, Ceilings, & Interior Moldings/Touch Up/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-05-10 15:14:57 :: BEDROOM WALL PANEL IS COMING LOOSE AND NEEDS TO BE STAPLED AND SEAM TAPE APPLIED Wall loose I added adhesive and also insure it was sticking to wall			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
	Notes			

Labor

Line# 2	Operation Code 60-136-15-00-001499	Operational Description Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-05-10 15:15:43 :: BLACK TANK FLUSH LEAKING Black water hose broke When running the black water flush i realized the line broke so i had a new line installed with a better fitting to make sure the line wouldn't bust			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes PHOTOS ARE REQUIRED FOR REVIEW DONE THANK YOU AUTHORIZED AS REQUESTED.			

Submitted	Labor Amt	\$55.50	Approved	Labor Amt	\$55.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$55.50		Total	\$55.50

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.