



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76666
Promised Date:
24 MAY 25



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 76666

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0514 BH TO CLOSE

Stock #: 11585
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 231MKS
Chassis #: 5ZT2CAMB0SU046102
Serial #: 5ZT2CAMB0SU046102
Mileage: 0
Licence:

Invoice #:
Date In: 05 MAY 25
Promised: 31 MAY 25
Date Sched:
Completed: 14 MAY 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: VIN check, checked all of the following condition of the battery and battery cables and connections, condition of the trailer coupler, the safety chain, operation of the tongue jack, running lights, brake lights, and turn signals, breakaway cable and brakes, Plug in the shore power cord, fresh water drain caps, wastewater cap and close waste system valves, inspect brake wires, shackles, axle, LP lines and clamp spacing, the underbelly for holes, gaps, and loose materials, Pressurize the city water system and check for leaks/missing caps on drain lines.. Inspect and clean out exterior appliance compartments (refrigerator, water heater, furnace), preformed a lp drop test and checked for leaks in lines, Check exterior lights, windows and vents for fit and finish.. Inspect storage compartment, emptied black and grey tanks

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Entry door

CORRECTION: Looked at door and moved screws over to make a better fit

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C



Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BEDROOM WALL PANEL IS COMING LOOSE AND NEEDS TO BE STAPLED AND SEAM TAPE APPLIED

CAUSE: Wall loose

CORRECTION: I added adhesive and also insure it was sticking to wall

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25

Subtotal for Job #2: 18.50

Job #3 - Warranty

COMPLAINT: BLACK TANK FLUSH LEAKING

CAUSE: Black water hose broke

CORRECTION: When running the black water flush i realized the line broke so i had a new line installed with a better fitting to make sure the line wouldn't bust

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Parts Part #	Description	Qty	Price	Total
72-0839	Fresh Water Adapter Fitting; BestPEX; 1/2 Inch PEX x 1/2 Inch Female Pipe Thread Plastic Swivel End Nut	1.00	3.17	3.17

Subtotal for Job #3: 40.17

Parts Total: 3.17
Labour Total: 55.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 58.67

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 May 2025

W/O: 76666
Promised Date: 31 MAY 25



Customer #: 1000
BASDENS AMERICAN RV,

