



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76667
Promised Date:
24 MAY 25

CUSTOMER WORK ORDER

WO #: 76667

Customer: 54447 - MILLER, KIMBERLY -
812-457-8209

Tag:

Author: BH

Location: 0616 BH TO CLOSE

Stock #: 11598

Stock Desc: 2025 TT ALLIANCE RV

DELTA 292RL

Chassis #: 7M5TD3321SC306346

Serial #: 7M5TD3321SC306346

Mileage: 0

Licence:

Invoice #:

Date In: 05 MAY 25

Promised: 31 MAY 25

Date Sched:

Completed: 16 JUN 25

Warr. Date: 19 MAY 25

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*76908 on 03 JUN 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: VIN check, checked all of the following condition of the battery and battery cables and connections, condition of the trailer coupler, the safety chain, operation of the tongue jack, running lights, brake lights, and turn signals, breakaway cable and brakes, Plug in the shore power cord, fresh water drain caps, wastewater cap and close waste system valves, inspect brake wires, shackles, axle, LP lines and clamp spacing, the underbelly for holes, gaps, and loose materials, Pressurize the city water system and check for leaks/missing caps on drain lines.. Inspect and clean out exterior appliance compartments (refrigerator, water heater, furnace), preformed a lp drop test and checked for leaks in lines, Check exterior lights, windows and vents for fit and finish.. Inspect storage compartment, emptied black

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

COMPLAINT: Transferred to BAS*76908 on 03 JUN 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Running lights brake lights emergency brakes and brakes work properly. Found two voids on roof filled with Dicor. Awning work properly and fabric intreat condition. Interior lights all work properly, outlets work properly, USB work properly. Stove and oven works properly microwave works properly refrigerator works properly all blinds and windows work properly. TV and antenna works properly fireplace works and tested both remotes. Water pump works properly. Did my LP drop test on the stove everything works properly. Black tank shut off doesn't work properly so I have to cut the belly lining and replace the valve. Factory smoke alarm wouldn't shut off so I installed a new one.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 54447
MILLER, KIMBERLY

PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1200 - Internal

COMPLAINT: Transferred to BAS*76908 on 03 JUN 25

Estimate amount was 0.00

INSTALL EQUALIZER 1200 WEIGHT DISTRIBUTION HITCH

CAUSE: Install equal-i-zer hitch

New hitch setup and adjusted

CORRECTION: Hung brackets on the camper frame and put rest of the hardware in side compartment for delivery hitch work

Leveled the camper then matched the ball height on the vehicle. Had to get a drop bar for the hitch.

Assembled the hitch then connected the vehicle to the camper. Checked the height and tightened the hardware. Connected the 7-way, coupler, breakaway cable and safety chains. Tested the running lights.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1200: 0.00

Job #1 - Warranty

COMPLAINT: THE BLACK TANK WILL NOT HOLD WATER

CAUSE: Black tank shut off no work

CORRECTION: Needing a 3 in blade ex valve is blocked due to sealer. Replaced with a new one and no leaks. Used under penning tage to leave a clean finish. Used spray foam to fill cracks and then painted black

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	370.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
T1003DSPB	BLADEX WASTE VALVE, 3IN, DRILLED STE	1.00	13.99	13.99

Subtotal for Job #1: 476.49

Job #2 - Warranty

COMPLAINT: THE CHAIR THE DINNETTE HAS SCRATCHES ON IT AND NEEDS REPLACED

CAUSE: BH PUT CHAIR IN THE CAMPER

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



W/O: 76667
Promised Date: 31 MAY 25



Customer #: 54447
MILLER, KIMBERLY



26451	Dinette Chair - Weaver Charcoal Fabr	1.00	80.99	80.99
-------	--------------------------------------	------	-------	-------

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - DINETTE CHAIR	1.00	26.21	26.21

Subtotal for Job #2: 144.20

Job #3 - Warranty

COMPLAINT: SMOKE ALARM WILL NOT STOP GOING OFF

CAUSE: Final pdi

CORRECTION: Factory smoke alarm would not shut off. So I installed a new one

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Parts

Part #	Description	Qty	Price	Total
03-0255	SMOKE ALARM	1.00	19.99	19.99

Subtotal for Job #3: 56.99

Job #4 - Warranty

COMPLAINT: FREEZER DOOR WILL NOT STAY LATCHED

CAUSE: Freezer door needs adjusted

CORRECTION: I adjusted the top hinge on the freezer door. Looks like it was loose and slide over. I checked it 5 times to make sure that it did not move. It is working as it should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	74.00

Subtotal for Job #4: 74.00

Parts Total:	114.97
Labour Total:	610.50
Sublet Total:	0.00
Extras Total:	26.21
WORK ORDER TOTAL:	751.68

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Jun 2025

