

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 2315994 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CATB5SN301421 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 300 / 300 ITEM # CAT281QBUNK-8-300 DEALER RO # 76673 CLAIM START DATE 05/29/2025 CLAIM END DATE 01/01/1900
---	---

Retail Date of Purchase	WARRANTY EXPIRATION DATE
--------------------------------	---------------------------------

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description	
20-69-02-00-000705	Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-05-29 16:11:22 :: THE OUTSIDE COMPARTMENT DOOR NEEDS ADJUSTD Door needs adjusted Took door off track and had to shim all 4 corners and also screw in new holes for screws now will shut properly		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 2

Operation Code	Operational Description	
30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-05-29 16:13:01 :: PANEL UNDER THE FRIDGE IS LOOSE Loose board Had too take off panel to find out the water heater had some wires and also pipes hitting against the wall to push out so readjusted the pipes and wires then put board back on the surface for a better fit		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 3

Operation Code	Operational Description	
20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-05-29 16:13:38 :: BATHROOM DOOR HITTIHNG THE LATCH Door hitting Moved and adjusted the door frame and latch so it will close correctly took all the screws out of wall and then put back together		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$55.50
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$55.50
Notes		

Submitted	Labor Amt	\$129.50	Approved	Labor Amt	\$129.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$129.50		Total	\$129.50

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.