



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76836
Promised Date:
24 MAY 25

CUSTOMER WORK ORDER

WO #: 76836 (Appointment Date: 23 MAY 2025 - Time: 10:30am)

Customer: 10308 - ROGERS, LINDA J. - Stock #: 11317

812-202-9509

Tag:

Author: BH

Location: 0620 BH TO CLOSE

Stock Desc: 2024 TT COACHMEN

FREEDOM EXPRESS 246RKS

Chassis #: 5ZT2FEPB1RW029057

Serial #: 5ZT2FEPB1RW029057

Mileage:

Licence:

Invoice #:

Date In: 15 MAY 25

Promised: 31 MAY 25

Date Sched:

Completed: 20 JUN 25

Warr. Date: 20 MAY 24

Job #1 - Internal

COMPLAINT: FRIDGE NOT GETTING COLD, FREEZER IS COOLING

CAUSE: Customer states refrigerator's not cooling

CORRECTION: I turned on the fridge and let it run for 4 hours. The fridge was set on 2 out of 5. With the fridge set on 2, the temp in the fridge was 42 degrees. The freezer was at 28 degrees. I set the fridge at 4 to see if it gets colder.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: A/C NOT COOLING FAN RUNS BUT COMPRESSOR DOES NOT

CAUSE: THE COMPRESSOR IS ONLY 7 AMPS

CORRECTION: NEED TO REPLACE THE A/C

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	277.50
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	277.50

Subtotal for Job #2: 555.00

Job #3 - Warranty

COMPLAINT: THE REAR AWNING ARM DID NOT GO IN ALL THE WAY

CAUSE: Is automaterial is bunching up in the middle. The rear awning arm needs to be shifted on the wall to the rear one inch to to be center with the with the rest of the arm.

CORRECTION: Need to shift awning arm on wall. Needs new awning canvas.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 10308
ROGERS, LINDA J.



Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	38.85
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	16.65

Subtotal for Job #3: 55.50

Job #4 - Internal

COMPLAINT: REPLACE THE MISSING STICK ON LEVEL

CAUSE: Needs front level changed. Glass is missing

CORRECTION: I replaced both of the levels. Front and side come in a kit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
14-8205	LEVEL STICK-ON 08525	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total: 0.00
 Labour Total: 610.50
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 610.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Jun 2025

W/O: 76836
 Promised Date: 31 MAY 25



Customer #: 10308
 ROGERS, LINDA J.

