



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76854
Promised Date:
20 MAY 25

CUSTOMER WORK ORDER

WO #: 76854

Customer: 49611 - WEBER, FELICIA -
765-918-7019

Tag:

Author: BH

Location: 0609 CHECK PREAUTH

Stock #: 11432

Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 291BRC

Chassis #: 4YDTSGP26S7100182

Serial #: 4YDTSGP26S7100182

Mileage:

Licence:

Invoice #:

Date In: 27 MAY 25

Promised: 30 MAY 25

Date Sched:

Completed: 30 MAY 25

Warr. Date: 30 MAY 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued properly, air pressure correct in all 5 tires. Running lights tail lights brakes and Emergency Brakes work. Installed a new battery. Battery disconnect is missing parts a won't stay together, so I took the screws out of one on the lot. (See photos) .after roof inspection I found a couple voids in the sealer. I filled them with Dicor self-leveling. Outside appliances looks good. Lp detector work properly. Refrigerator stove and microwave works properly. Flushed all water lines added water to fresh tank ran water pump. Had to put cover back over water pump and removed winterize liquid jug that was still connected for winterize process. Water pump works properly. Have to adjust bathroom latch the door won't stay shut. Lp drop test on outside port with water heater and stove on. Gauge shows with those two running 10 and needs to be 11 and regulator is maxed out. So I replaced with a new one. Did my new lp drop test everything works properly now. Had to fix the piece of trim by the door it was loose. Got it fixed properly. Replaced winterize panel that was left out. Put wire lume back on properly that was coming off

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1200 - Internal

COMPLAINT: INSTALL EQUALIZER 1200 WEIGHT DISTRIBUTION HITCH

CAUSE: Equalizer hitch work

New hitch setup and adjustment

CORRECTION: Installed the equalizer brackets to camper and have to move lp tanks forward because cover is resting on hitch brackets.

Leveled the camper then checked the height and matched the truck. Connected the camper to the truck and adjusted as needed. Connected the 7-way, coupler, breakaway cable and safety chains. Tightened all hardware.

Labor



Customer #: 49611
WEBER, FELICIA



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
14-2928	12,000LB. EQUALIZER ADJ HITCH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1200: 0.00

Job #AIRLIFT2 - Internal

COMPLAINT: INSTALL AIRLIFT SPRING KIT W/COMPRESSOR AND WIRELESS REMOTE KIT

CAUSE: The customer wants airbag system installed.

CORRECTION: I installed air compressor with remote control. I installed an airbag kit on rear axle. I added an emergency fill on the rear bumper by license plate.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
25980EZ	25980EZ WIRELESS ONE 2ND GENERATION	1.00	N/C	N/C
88365	88365 09-18 RAM 1500 (DRILLING REQUI	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
FRT	FREIGHT	1.00	N/C	N/C

Subtotal for Job #AIRLIFT2: 0.00

Job #1 - Internal

COMPLAINT: SWAP TV BRACKETS (2) TRADE BR TO BUNKHOUSE ----TRADE LR TO LR

CAUSE: Removed TVs from trade in unit and remount in new unit...

CORRECTION: Removed TVs from living room and bedroom, remounted in Bunkroom and living room.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

WILL DROP TRUCK + TRADE OFF THURDAY MORNING



W/O: 76854
Promised Date: 30 MAY 25



Customer #: 49611
WEBER, FELICIA



Subtotal for Job #2: 0.00

Job #4 - Warranty

COMPLAINT: REGULATOR WILL NOT ADJUSTED ANY HIGHER

CAUSE: Regulator bad

CORRECTION: Regulator would not adjust it was maxed out so I replaced with a new one to get to my spev

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	90.00

Parts Part #	Description	Qty	Price	Total
06-0443	MEGR-253P LP REGULATOR 2-STAGE	1.00	63.62	63.62

Subtotal for Job #4: 153.62

Job #5 - Warranty

COMPLAINT: TRIM BY THE ENTRY DOOR IS LOOSE

CAUSE: Wall trim by door loose

CORRECTION: Used a stapel to fasten wall trim a d filled holes with putty.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	18.00

Subtotal for Job #5: 18.00

Parts Total: 63.62
Labour Total: 108.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 171.62

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Jun 2025

