

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 76935
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11607 - 2025 COUGAR 320RDS 4YDFCGR2XS2507006
VIN: 4YDFCGR2XS2507006 HIN: SER#: 4YDFCGR2XS2507006
Mileage: 0 Work Order Comp: 31 JUL 25
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 04 JUN 25 Inv #: 420535

WO # Job # Description JOB INFORMATION

76935 1 TABLE IS NOT MOUNTED TO THE WALL
table not mounted to wall in living room
left side of table mount screws had become loose and stripped of
their spots. had to adjust table over slightly to put new holes
in for table to become secure in place

76935 2 ENTRY DOOR WILL NOT LATCH
entry door will nopt latch
entry door was not latching. bent striker plate slightly and saw
screen door was not catching on door. adjusted were scrrren door
sat on entry door. screen and entry door shut easy now

76935 3 FRIDGE LOCK DOES NOT LINE UP
loose fridge lock
went to fridge took out two bolts holding together bracket. tried
to adjust fron of bracket without taking fridge out but it did
not work. had to remove fridge to adjust bracket from behind by
taking out bottom plate holding fridge as well. pulled the fridge
out adjusted bracket over closer to fridge. put fridge back in
place and attached front bar on top of fridge and bottom of
fridge to secure back in place.

76935 4 THE ENTERTAINMENT CENTER HAS A SCRATCH ON IT.
entertainment center has scratch on it
found scratch on right side of entertainment center. applied old
english to the scratch and filled in and is no longer visable

Claim : 76935

```

*****
WO #      Job #   Description      JOB INFORMATION
*****

```

```

76935      5     THERE IS A SCRATCH ON BEDROOM SLIDING GLASS DOOR
           scratches on bedroom glass sliding door
           found three scratches on trim of glass bedroom closet door.
           filled in scratches with black paint. no longer visable

```

```

*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      1     MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990      1     MISCELLANEOUS REPAIR      0.30      180.00      54.00
Z990      2     MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990      2     MISCELLANEOUS REPAIR      0.20      180.00      36.00
Z990      3     MISCELLANEOUS REPAIR      0.40      180.00      72.00
Z990      4     MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990      4     MISCELLANEOUS REPAIR      0.20      180.00      36.00
Z990      5     MISCELLANEOUS REPAIR      0.01      180.00      1.80
Z990      5     MISCELLANEOUS REPAIR      0.09      180.00      16.20

```

```

Parts Total:      0.00
Labour Total:     216.00
Sublet Total:     0.00
Extras Total:     0.00

```

>>>> Claim Total: 216.00

Customer Signature: _____

Date: _____