

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
<b>BASDEN RV CENTER INC</b>		<b>CLAIM</b>	2351522
<b>DBA AMERICAN RV CENTER</b>		<b>CLAIM ORIGIN</b>	WEB
<b>600 E BASELINE ROAD</b>		<b>ORIGINAL CLAIM ID</b>	
<b>EVANSVILLE, IN 47725</b>		<b>VIN</b>	4X4TCKB21TK096299
<b>USA</b>		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$185.00	<b>SITE/WAREHOUSE</b>	094 / 094A
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	CKT26DBH-94
		<b>DEALER RO #</b>	77048
		<b>CLAIM START DATE</b>	06/30/2025
		<b>CLAIM END DATE</b>	01/01/1900

Retail Date of Purchase \_\_\_\_\_ WARRANTY EXPIRATION DATE \_\_\_\_\_

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-102-01-00-001118	Miscellaneous Interior Trim, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-30 16:03:26 :: STAPLE HOLES Staple holes Got some wood putty to cover up holes and then smoothed it over with a towel			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$18.50
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$18.50
	<b>Notes</b>			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-101-02-00-001076	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-30 16:04:45 :: BEDROOM DOOR IS NOT SHUTTING Bathroom door Noticed bathroom door wasn't shutting properly so moved the position where the latch is so the door would shut properly			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$37.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$37.00
	<b>Notes</b>			

### Labor

<b>Line# 3</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-91-15-00-004713	Furniture/Fabric Tack - Interior/Living Quarters, Sofa, Chair/Repair or Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-30 16:06:14 :: SMALL STAIN ON THE COUCH Stain on couch Took a towel and some mineral spirits and gently rub on stain and it came out with the solution			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$18.50
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$18.50
	<b>Notes</b>			

### Labor

<b>Line# 4</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	40-196-01-11-001274	Single Pancake Light - Electrical/12 Volt Interior/Replace/Electrical		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-30 16:08:29 :: LIGHT IN BEDROOM FLICKERING Light flickering The light was flickering due to the cap that was sitting on top of the connection making it where the switch was being bumped and took off cover readjusted it where the button was out and not causing the			

flickering to happen  
**Model#** Dlr Sub Hrs 0.20 Sub Labor Amt \$37.00  
**Serial#** Appr Hrs 0.20 Appr Labor Amt \$37.00  
**Notes**

**Labor Line# 5**  
**Operation Code** 60-141-01-00-001618  
**Operational Description** Shower Head, Hose Assembly - Plumbing/Shower, Tub Surround/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2025-06-30 16:09:12 :: SHOWER HEAD LEAKING Shower head . The shower head was leaking due to the regulator being put in upside down so I took it out and re attached the shower head now isn't leaking

**Model#** Dlr Sub Hrs 0.10 Sub Labor Amt \$18.50  
**Serial#** Appr Hrs 0.10 Appr Labor Amt \$18.50

**Notes**

**Labor Line# 6**  
**Operation Code** 20-66-02-00-000664  
**Operational Description** Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2025-06-30 16:10:53 :: REAR ENTRY DOOR Rear entry door Fixed the rear entry door by moving latch over slightly from rubbing now will shut smoother

**Model#** Dlr Sub Hrs 0.30 Sub Labor Amt \$55.50  
**Serial#** Appr Hrs 0.30 Appr Labor Amt \$55.50

**Notes**

Submitted			Approved		
Labor Amt	\$185.00		Labor Amt	\$185.00	
Parts & Freight	\$0.00		Parts & Freight	\$0.00	
Total	\$185.00		Total	\$185.00	

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.