



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77048
Promised Date:
20 JUN 25

CUSTOMER WORK ORDER

WO #: 77048

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0630 SEE IF JEREMY HAS
PICS

Stock #: 11622
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE GREY WOLF 26DBH
Chassis #: 4X4TCKB21TK096299
Serial #: 4X4TCKB21TK096299
Mileage: 0
Licence:

Invoice #:
Date In: 17 JUN 25
Promised: 30 JUN 25
Date Sched:
Completed: 30 JUN 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi new

CORRECTION: VIN check, checked all of the following condition of the battery cables and connections, condition of the trailer coupler, the safety chain, operation of the tongue jack, running lights, brake lights, and turn signals, breakaway cable and brakes, Plug in the shore power cord, fresh water drain caps, wastewater cap and close waste system valves, inspect brake wires, shackles, axle, LP lines and clamp spacing, the underbelly for holes, gaps, and loose materials, Pressurize the city water system and check for leaks/missing caps on drain lines.. Inspect and clean out exterior appliance compartments (refrigerator, water heater, furnace), preformed a lp drop test and checked for leaks in lines, Check exterior lights, windows and vents for fit and finish.. Inspect storage compartment, emptied black and grey

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: STAPLE HOLES

CAUSE: Staple holes

CORRECTION: Got some wood putty to cover up holes and then smoothed it over with a towel

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Customer #: 1000
BASDEN'S AMERICAN RV,





Subtotal for Job #1: 18.50

Job #2 - Warranty

COMPLAINT: BEDROOM DOOR IS NOT SHUTTING

CAUSE: Bathroom door

CORRECTION: Noticed bathroom door wasn't shutting properly so moved the position where the latch is so the door would shut properly

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: SMALL STAIN ON THE COUCH

CAUSE: Stain on couch

CORRECTION: Took a towel and some mineral spirits and gently rub on stain and it came out with the solution

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #3: 18.50

Job #4 - Internal

COMPLAINT: FURANCE FAN SOUNDS BAD

CAUSE: Water heater

CORRECTION: Opened up the compartment where the heater sits and found out a hose wasn't completely in the system so I took a small screwdriver and also put it back where it needed to go now when turned on doesn't make that sound it did before

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: LIGHT IN BEDROOM FLICKERING

CAUSE: Light flickering

CORRECTION: The light was flickering due to the cap that was sitting on top of the connection making it where the switch was being bumped and took off cover readjusted it where the button was out and not causing the flickering to happen

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #5: 37.00

Job #6 - Warranty

COMPLAINT: SHOWER HEAD LEAKING

CAUSE: Shower head





CORRECTION: The shower head was leaking due to the regulator being put in upside down so I took it out and re attached the shower head now isn't leaking

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #6:			18.50

Job #7 - Warranty
COMPLAINT: REAR ENTRY DOOR

CAUSE: Rear entry door

CORRECTION: Fixed the rear entry door by moving latch over slightly from rubbing now will shut smoother

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	92.50
Subtotal for Job #7:			92.50

Job #8 - Internal
COMPLAINT: HOLES IN SLIDEROOM TRIM

CAUSE: Holes in trim

CORRECTION: Took some wood putty to fill in holes left behind from factory and then smoothed out with a brown paper towel

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #8:			0.00

Job #9 - Internal
COMPLAINT: TV MOUNT NOT SCREWED IN

CAUSE: Screws not in

CORRECTION: Took my screw gun and tightened 3 of 6 screws in the TV mount that wasn't properly installed

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #9:			0.00

Job #10 - Internal
COMPLAINT: STAIN ON TOILET BOTTOM

CAUSE: Stain

CORRECTION: Took a towel and hot water with some dawn soap and the stain came off the toilet and now looks better

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #10:			0.00



W/O: 77048
Promised Date: 30 JUN 25

Parts Total:	0.00
Labour Total:	222.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	222.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Jun 2025



Customer #: 1000
BASDEN'S AMERICAN RV,

