



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77080
Promised Date:
20 JUN 25

CUSTOMER WORK ORDER

WO #: 77080

Customer: 55929 - BUEHRENS, JAMES -
812-454-6458

Tag:

Author: BH

Location: 1201 CALL CUSTOMER AGAIN

Stock #: 11471

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT SERIES 184BHS

Chassis #: 5ZT2CAGC9SK009212

Serial #: 5ZT2CAGC9SK009212

Mileage:

Licence:

Invoice #:

Date In: 19 JUN 25

Promised: 30 JUN 25

Date Sched:

Completed: 30 NOV 25

Warr. Date: 23 JUN 25

Job #FPDINTT - Internal

Transferred to BAS*77152 on 27 JUN 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

Transferred to BAS*77152 on 27 JUN 25

Estimate amount was 0.00

DELUXE STARTER KIT

Subtotal for Job #DELUXE: 0.00

Job #BCWT - Internal

Transferred to BAS*77152 on 27 JUN 25

Estimate amount was 0.00

INSTALL DIGITAL, PROPORTIONAL BRAKE CONTROL IN TRUCK/SUV

Labor

Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BCWT: 0.00

Job #1 - Warranty

COMPLAINT: CITY WATER CHECK VALVE IS BAD

CAUSE: Water coming out the city water inlet

CORRECTION: When i was running the water pump water was coming out the city water inlet. The check valve was bad. So I replaced it and it works properly now.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Printed On: 12/3/2025 11:06:28AM

© 2025 Integrated Dealer Systems



Page 1 of 2

Customer #: 55929
BUEHRENS, JAMES

Z990 MISC LABOUR CODE (EXTERNAL) JTW 55.50

Parts

Part #	Description	Qty	Price	Total
10-1103	62145 PW PLASTIC MPT CITY WATER FLAN	1.00	14.70	14.70

Subtotal for Job #1: 70.20

Job #2 - Warranty

COMPLAINT: 2 DECALS ARE DAMAGED AND NEED REPALECD

CAUSE: FOUND ORN PLACES ON DECALS

CORRECTION: REMOVE AND REPLACE THE DECALS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	111.00

Parts

Part #	Description	Qty	Price	Total
F100418579	GRAPHIC, #14 ODS "CATALINA" LOGO 202	1.00	10.21	10.21
F100597137	GRAPHIC, #44 "SUMMIT SERIES" SIDE MI	1.00	10.57	10.57

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECALS	1.00	15.68	15.68

Subtotal for Job #2: 147.46

Parts Total: 35.48
Labour Total: 166.50
Sublet Total: 0.00
Extras Total: 15.68
WORK ORDER TOTAL: 217.66

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Dec 2025

W/O: 77080
Promised Date: 30 JUN 25



Customer #: 55929
BUEHRENS, JAMES

