



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75611
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75611 (Appointment Date: 03 DEC 2024 - Time: 07:00am)

Customer: 52875 - SEILER, KODY -
812-589-9127

Tag: BH - PARTS ORDERED 12-16

Author: BH

Location: 0122 BH TO CLOSE

Stock #:

Stock Desc: 2022 5W FOREST RIVER

WILDWOOD 295BH

Chassis #:

Serial #: 4X4FWBF2XNV706331

Mileage:

Licence:

Invoice #: 413409

Date In: 03 DEC 24

Promised: 31 DEC 24

Date Sched:

Completed: 23 JAN 25

Warr. Date:

Job #1 - External

COMPLAINT: SHOWER GLASS BROKEN IN THE BATH ROOM THERE IS GLASS EVERYWHERE WILL HAVE TO BE CLEANED

CAUSE: shower glass is broken

CORRECTION: cleaned glass up it was everywhere, filled out sheet to get pricing, took apart crate to get to doors, had to take off bathroom door, took off shower doors and other glass, took apart frame because it would not come out together. cleaned off old silicone. had to take toilet out and reinstall to get shower surround in and set. screwed in side walls to wall, installed both doors and adjusted for proper fit, and tested opening and closing back and forth. then sealed both walls inside with silicone, like old one was.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
10191	CURVED GLASS SHOWER DOOR ASSEMBLY, 3	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
FRT	SHIPPING-SHOWER DOOR	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: LED ABOVE THE MAIN SLIDE ROOM IS NOT WORKING CUSTOMER MARKED THE SWITCH WITH BLUE TAPE

CAUSE: main slide lights dont work

CORRECTION: found lights had fallen and wires were pulled out, plugged wires back in and light works but the sticky stuff has dirt on it and wont stick back in track, needs new lights, filled out sheet to get pricing. ran room out to get to track for lights, hooked up power to lights and installed lights into track, all good.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts



Customer #: 52875
SEILER, KODY

W/O: 75611
Promised Date: 31 DEC 24



Customer #: 52875
SEILER, KODY



Part #	Description	Qty	Price	Total
10194	144" WHITE LED LIGHT STRIP	1.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-LIGHTS	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - External

COMPLAINT: THE SLIDING DOOR FOR THE CLOSET IN THE BEDROOM THE VINEL IS COMING LOOSE AND FALLING OFF MARKED WITH TAPE

CAUSE: sliding door on bedroom closet,paper is coming off

CORRECTION: took measurements and filled out sheet.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING-CLOSET DOORS	0.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CAUSE: recall in quick connect

CORRECTION: took off old one and installed new one and did leak test.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	51.00
Subtotal for Job #22V243:			51.00

Parts Total:	0.00
Labour Total:	51.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Jan 2025

